

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20007272/UKS3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900140984

**Claimant**  
**Vehicle No :** FBK1799R **Insured Vehicle No :** SKV2201C

Date of Loss: 10/07/2020 Nature of Claim: TP Claim No: 5239465987SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBK1799R</b>	Engine No:	E3F5E038549
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBPRI101000053740
Reg. Date:	13/04/2015 (Man. Year: 2015)	Odometer:	61725 km
Colour:	Red/Black		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,174.00	1,881.90	292.10	13.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	434.00	335.00	99.00	22.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,608.00</b>	<b>2,216.90</b>	<b>391.10</b>	<b>15.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,750.00</b>		
<b>(\$\$)</b>	2,608.00	1,750.00	858.00	32.90
<b>+ GST 7.00/7.00% (\$\$)</b>	182.56	122.50	60.06	32.90
<b>Nett Amount (\$\$)</b>	<b>2,790.56</b>	<b>1,872.50</b>	<b>918.06</b>	<b>32.90</b>
<b>+ Loss of Use (3.0 x S\$20.00/day) (\$\$)</b>		60.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,934.50</b>		

### INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 14/07/2020 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Serviceable	48.00 F	*- FL
2	1		*BRACKET MUDGUARD FRONT	Bent	24.00 F	*24.00 FL
3	1		*BRACKET UNDER FORK	Bent	180.00 F	*180.00 FL
4	1		*CRASH BAR	Bent	203.00 F	*203.00 FL
5	1		*FORK FRONT ASSY LH	Bent	625.00 F	*625.00 FL
6	1		*FORK FRONT ASSY RH	Bent	625.00 F	*625.00 FL
7	1		*HEADLAMP ASSY	Cracked	147.00 F	*147.00 FL
8	1		*LAMP SIGNAL FRONT LH	Cracked	21.00 F	*21.00 FL
9	1		*MIRROR LH	Cut	35.00 F	*35.00 FL
10	1		*MIRROR RH	Serviceable	35.00 F	*- FL
11	1		*MUDGUARD FRONT (RED)	Cracked	97.00 F	*97.00 FL
12	1		*STAY HEADLAMP	Bent	68.00 F	*68.00 FL
13	1		*SET STEERING CONE	Necessary	66.00 F	*66.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,174.00</b>	<b>2,091.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>209.10</b>
<b>Total Parts (\$\$)</b>	<b>2,174.00</b>	<b>1,881.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR	New	378.00	300.00
<b>Gross Labour Cost (\$)</b>			<b>434.00</b>	<b>335.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**