

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007273/DRS3Q2
Date: 26/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100341337
Claimant Vehicle No :	SHC7767P	Insured Vehicle No :	SKJ9897L
Date of Loss:	12/07/2020	Nature of Claim:	TP
		Claim No:	7674546808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7767P		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU192193
Reg. Date:	30/04/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU141416
Colour:	Yellow	Odometer:	77208 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,688.80	8,352.16	4,336.64	34.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,650.00	1,780.00	51.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,118.80	10,002.16	6,116.64	37.95
+ GST 7.00/7.00% (S\$)	1,128.32	700.15	428.17	37.95

Nett Amount (S\$)	17,247.12	10,702.31	6,544.81	37.95
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$125.19/day) (S\$)		1,126.71		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		12,366.47		

INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 14/07/2020

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Bent	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Deformed	187.40 FL	*187.40 FL
3	2		*BOOT LID HINGE (LH/RH)	Not Necessary	142.60 FL	*- FL
4	2		*BOOT LID ABSORBER (LH/RH)	Not Necessary	173.40 FL	*- FL
5	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
7	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
8	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
9	1		*BOOT LID LAMP (RH)	Mtg Broken	794.40 FL	*794.40 FL
10	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
11	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
12	1		*BOOT LID TRIMBOARD CENTRE	Not Necessary	159.60 FL	*- FL
13	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
14	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
15	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
16	1		*REAR BUMPER	Dented / Distorted	459.40 FL	*459.40 FL
17	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
18	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	O/S Bent / N/S Not Necessary	376.20 FL	*188.10 FL
19	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted / Cut	451.25 FL	*451.25 FL
20	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Bent / Mtg Broken	47.50 FL	*47.50 FL
21	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Serviceable	171.60 FL	*- FL
23	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
24	1		*REAR BUMPER UNDER CENTRE	Bent / Deformed	123.85 FL	*123.85 FL
25	1		*REAR BUMPER SIDE UNDER (LH/RH)	O/S Broken / N/S Not Necessary	246.20 FL	*123.10 FL
26	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
27	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
28	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
29	2		*LICENCE LAMP (LH/RH)	Not Necessary	170.60 FL	*- FL
30	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
31	1		*TAIL LAMP (RH)	Mtg Broken	870.40 FL	*870.40 FL
32	1		*TAIL LAMP QUARTER PANEL (RH)	Not Necessary	208.90 FL	*- FL
33	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
34	1		*REAR PANEL GARNISH	Mtg Deformed	346.80 FL	*346.80 FL
35	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
37	1		*SPARE TYRE PANEL	Repair	892.50 FL	*- FL
38	1		*MEMBER ASSY -REAR FLOOR CENTRE	Not Necessary	863.50 FL	*- FL
39	2		*PANEL ASSY -REAR FLOOR SIDE (LH/RH)	Not Necessary	78.80 FL	*- FL
40	1		*REAR TRAY TOOLS BOX RH	Broken	675.30 FL	*675.30 FL
41	1		*REAR TRAY TOOLS BOX LH	Deformed	693.20 FL	*693.20 FL
42	1		*REAR TRAY LUGGS CENTER	Mtg Deformed / Broken	354.20 FL	*354.20 FL
43	1		*EXHAUST PIPE INSULATOR	Not Necessary	235.00 FL	*- FL
44	1		*EXHAUST SILENCER	Dented / Bent	943.50 FL	*943.50 FL
45	1		*EXHAUST PIPE HANGE	Not Necessary	29.20 FL	*- FL
46	1		*BOOT LID CITY CAB LOGO & TEL NO.STICKER	Necessary	35.00 FS	*35.00 FS
47	1		*REAR NO.PLATE +TRIM COVER	Cracked	45.00 FS	*45.00 FS
48	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
49	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
50	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
51	1		*SPARE TYRE PANEL TOP COVER SILICON	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,709.50	10,351.20
- List Item Discount on L Items 20.00/20.00% (S\$)	3,020.70	1,999.04
Total Parts (S\$)	12,688.80	8,352.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	140.00	30.00
4	TUFF KOTE	New	140.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE /REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			3,430.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >