

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007274/REA3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070081776
Claimant Vehicle No :	GBE2280U	Insured Vehicle No :	GBJ6282L
Date of Loss:	11/07/2020	Nature of Claim:	TP
		Claim No:	8470563389SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE2280U		
Make & Model:	TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD LGV (M)	Engine No:	1KD2548341
Reg. Date:	02/10/2015 (Man. Year: 2015)	Chassis No:	KDH2015018957
Colour:	Red	Odometer:	122657 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,732.38	1,231.77	1,500.61	54.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	580.00	1,000.00	63.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,312.38	1,811.77	2,500.61	57.99
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,312.38	1,550.00	2,762.38	64.06
+ GST 7.00/7.00% (S\$)	301.87	108.50	193.37	64.06
Nett Amount (S\$)	4,614.25	1,658.50	2,955.75	64.06
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	13/07/2020	
Date Inspected:	17/07/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road Singapore 609286
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	571.60 FL	*571.60 FL
2	10		*CLIP FRONT BUMPER	Necessary	38.90 FL	*38.90 FL
3	1		*L/FR SIDE RETAINER	*Check	168.02 FL	*- FL
4	1		*L/FRONT DOOR	Repair	1,739.46 FL	*- FL
5	1		*LEFT HEADLAMP ASSY	Scratched	885.20 FL	*885.20 FL
6	1		*STICKER-COMPANY LETTERING	Necessary	30.00 FS	*30.00 FS
7	1		*STICKER-NINJA VAN WORDING	Necessary	150.00 FS	*80.00 FS
					Sub Total (\$\$)	3,583.181,605.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	850.80373.93
					Total Parts (\$\$)	2,732.381,231.77

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE,RE-ALIGN;FR BUMPER,RH FR DOOR AND AFFECTED AREA	New	800.00	300.00
2	TO PUTTY,SPRAY PAINT;RH FR DOOR	New	600.00	250.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE,RE-FIT RH FR DOOR WINDOW GLASS,REGULATOR MOTOR,DOOR TRIM TO FACILITATE REPAIR	New	150.00	0.00
Gross Labour Cost (\$)			1,580.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >