COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286) Tel: 68676919 Fax: 62626950 Appendix A

| are Parts enicle No. : _ | G | BE2280U | Submit By | : | C. W WONG | |
|---------------------------|---------------|--------------|--------------------|---|------------|--|
| ake & Model : | TOYOTA | HIACE 3.0 DX | Year Manufacture : | | 2015 | |
| hassis No. : _ | KDH2015018957 | | Engine No. | : | 1KD2548341 | |
| ,11000 | | | | | TP | |

S/Order : ____

| | | S/Ord | aer | : | | | |
|-----|-----------------------------------|-------|---------------|---------------|---------------|------------------|---------------------------|
| No. | Part Description | Qty | Cost Price | Nett Price | List Price | S- Nett Price | Diposition By Surveyor |
| 1 | FRONT BUMPER de - | 1 | | | \$571.60 | | |
| _ | CLIP FRONT BUMPER ALL / | 10 | | | \$38.90 | | |
| 3 | L/FR SIDE RETAINER ? | 1 | | | \$168.02 | | |
| _ | L/FRONT DOOR Capair | 1 | | | \$1,739.46 | | |
| 5 | STICKER - COMPANY LETTERING NEW / | 1 | | | | \$30.00 | |
| 6 | STICKER – NINJA VAN WORDING | 1 | | | | \$150.00 | 180 |
| 7 | LEFT HEADLAMP ASSY SUL/ | 1 | | | \$885.20 | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |
| 13 | | | | | | | |
| 14 | | | | | | | |
| 15 | | | | | | | |
| 16 | | | | | | | |
| 17 | | | | | | | |
| 18 | | | | | | | |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | I |
| 23 | | | | | | | |
| 24 | | | 0 | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | 1 |
| 29 | | | | 1 | | | 1 |
| 30 | | | | | | | |

lote: If any of the quoted parts are recommended to be repaired, then an additional labour charge vill be charged accordingly under supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386) Tel: 68676919 Fax: 62626950,68676903

| Lal | 00 | u | r |
|-----|----|---|---|
|-----|----|---|---|

| Vehicle No. | : | GBE2280U | Submit By | 2 | : | C. W WONG | |
|--------------|---|----------|----------------------|---|---|-----------|--|
| Make & Model | : | TOYOTA | Year of Manufacture: | | | 2015 | |

| wake t | Model: TOYOTA Year of Manufacture: | X II | 2015 |
|--------|--|-------------------|-------------------|
| S/No | Labour Description | Esimated Price | Adjusted Price |
| 1 | TO REMOVE & REPLACE, RE ALIGN :FR BUMPER ,RH FR DOOR AND AFFECTED AREA | \$800.00 | 300 |
| 2 | TO PUTTY, SPRAY PAINT :RH FR DOOR | \$600.00 | 250 |
| 3 | TO CHECK WIRING | \$30.00 | 30 |
| 4 | TO REMOVE,RE FIT RH FR DOOR WINDOW GLASS,REGULATOR "MOTOR,DOOR TRIM TO FACILILATATE REPAIR | \$150.00 | X |
| | | | |
| | | | |
| | | | |
| | | | |
| | | , | |
| | | | |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING 45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

| Our Ref: | | | | | | | |
|--|---------------|---------------------------|------|-----------------------|--|--|--|
| Type of Claim : Own Damag | e | Vehicle No. | : | GBE2280U | | | |
| X 3rd Party | | Make & Model | : | TOYOTA / HIACE 3.0 DX | | | |
| Windscreen | | Year of Manufacture | : | 2015 | | | |
| | | Chassis No. | : | KDH2015018957 | | | |
| Ins Company : AIG II | NS | Engine No. | : | 1KD2548341 | | | |
| Excess : | | Policy No. | 1 | | | | |
| Date of Accident : 11/07/3 | 2020 | Time of Accident | : | 09.00 A.M | | | |
| Suggested Days of Repair : | 5 DAY | In-house Vehicle Assessor | | | | | |
| Repair Estimates | | Name | : | C. W WONG | | | |
| | | Signature | : | | | | |
| Parts (a) Cost Price Items | \$3,403.18 | Contact No | : | 68676919 Or 97239882 | | | |
| Less 25 % | \$(850.79) | | | | | | |
| | | | | | | | |
| (b) Nett Price Items | | | | | | | |
| Less % | | | | | | | |
| (c) Special Nett Items | \$180.00 | | | | | | |
| Total Parts Cost (Appendix A) | \$2,732.39 | | | | | | |
| Labour (Appendix B) | \$1,580.00 | | | | | | |
| Total Repair Cost | \$4,312.39 | | | | | | |
| The above total will be subjected to 7% | % G.S.T. | | | | | | |
| | | | | | | | |
| Name of Surveyor | : RASUL | - Hp 9001006 | 8 | | | | |
| Company | : LKK | | | | | | |
| Survey conducted on | : 17/07/2 | oloat | | 1648 | | | |
| Remarks By Surveyor | | | | | | | |
| (a) The repair of this vehicle is authorized / is not authorized until further notice. | | | | | | | |
| | | | | | | | |
| (b) Recommended Days of Repair | cpair/Lumpsum | | | | | | |
| (c) Resurvey : Required Not Required a flor regard / Lung 1888 | | | | | | | |
| (d) Excess :\$_ | | | | | | | |
| (e) Signature of surveyor | : Jan | Da | ite: | 17/67/2020 | | | |

ACCIDENT REPAIR ESTIMATES (3)

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: