

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jul 2020 Edit Reg		14 Jul 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: GOH SIOW MONG , ID: S7615942D									
Main Claimant: WU SEE KIAT , ID: S0051939A									
Vehicle Reg. No.: SMC7362P		Date of Loss: 09/07/2020 00:00 - :59 [23 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0923290103SG		Policy/Cover Note No.: 2100509474 (Comprehensive)							
Vehicle Reg. No. (Insured): SLN8507L		Policy No. (Claimant):							
		Excess:							
Repairer: Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY , # 01-52, 417883 Kaki Bukit - Tel: 91993103									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (15/07/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC7362P (0923290103SG)**
[SLN8507L]

TP

WU SEE KIAT
Jul 9 2020 12:00AM
[GOH SIOW MONG]
Safe Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/07/20 21:12	General View	 Load JPG	☒
2	14/07/20 21:12	General View	 Load JPG	☒
3	14/07/20 21:12	General View	 Load JPG	☒
4	14/07/20 21:12	General View	 Load JPG	☒
5	14/07/20 21:12	General View	 Load JPG	☒
6	14/07/20 21:12	General View	 Load JPG	☒
7	14/07/20 21:12	General View	 Load JPG	☒
8	14/07/20 21:12	General View	 Load JPG	☒
9	14/07/20 21:12	General View	 Load JPG	☒
10	14/07/20 21:12	General View	 Load JPG	☒
11	14/07/20 21:12	General View	 Load JPG	☒
12	14/07/20 21:12	General View	 Load JPG	☒
13	14/07/20 21:12	General View	 Load JPG	☒
14	14/07/20 21:12	General View	 Load JPG	☒
15	14/07/20 21:12	General View	 Load JPG	☒
16	14/07/20 21:12	General View	 Load JPG	☒
17	14/07/20 21:12	General View	 Load JPG	☒
18	14/07/20 21:12	General View	 Load JPG	☒
19	14/07/20 21:12	General View	 Load JPG	☒
20	14/07/20 21:12	General View	 Load JPG	☒
21	14/07/20 21:12	General View	 Load JPG	☒
22	14/07/20 21:12	General View	 Load JPG	☒
23	14/07/20 21:12	General View	 Load JPG	☒
24	14/07/20 21:12	General View	 Load JPG	☒
25	14/07/20 21:12	General View	 Load JPG	☒
26	14/07/20 21:12	General View	 Load JPG	☒
27	14/07/20 21:12	General View	 Load JPG	☒
28	14/07/20 21:12	General View	 Load JPG	☒
29	14/07/20 21:12	General View	 Load JPG	☒
30	14/07/20 21:12	General View	 Load JPG	☒
31	14/07/20 21:12	General View	 Load JPG	☒
32	14/07/20 21:12	General View	 Load JPG	☒
33	14/07/20 21:12	General View	 Load JPG	☒
34	14/07/20 21:12	General View	 Load JPG	☒
35	14/07/20 21:12	General View	 Load JPG	☒
36	14/07/20 21:12	General View	 Load JPG	☒
37	14/07/20 21:12	General View	 Load JPG	☒
38	14/07/20 21:12	General View	 Load JPG	☒
39	14/07/20 21:12	General View	 Load JPG	☒
40	14/07/20 21:12	General View	 Load JPG	☒

Photos/Images			3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	14/07/20 21:12	Odometer Reading		Load JPG	☒
42	14/07/20 21:12	Chassis Number		Load JPG	☒
43	14/07/20 21:12	General View		Load JPG	☒
44	14/07/20 21:12	General View		Load JPG	☒
45	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
46	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
47	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
48	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
49	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
50	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
51	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
52	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
53	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
54	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
55	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
56	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
57	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
58	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
59	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
60	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
61	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
62	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
63	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
64	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
65	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
66	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
67	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
68	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
69	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
70	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
71	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
72	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
73	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
74	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
75	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
76	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
77	15/07/20 17:18	Photographs of Damaged Parts		Load JPG	☒
78	17/07/20 20:39	Photo After Spray		Load JPG	☒
79	17/07/20 20:39	Photo After Spray		Load JPG	☒
80	17/07/20 20:39	Photo After Spray		Load JPG	☒
81	17/07/20 20:39	Photo After Spray		Load JPG	☒
82	17/07/20 20:39	Photo After Spray		Load JPG	☒
83	17/07/20 20:39	Photo After Spray		Load JPG	☒
84	17/07/20 20:39	Photo After Spray		Load JPG	☒
85	17/07/20 20:39	Photo After Spray		Load JPG	☒
86	17/07/20 20:39	Photo After Spray		Load JPG	☒
87	17/07/20 20:39	Photo After Spray		Load JPG	☒
88	17/07/20 20:39	Photo After Spray		Load JPG	☒
89	17/07/20 20:39	Photo After Spray		Load JPG	☒
90	17/07/20 20:39	Photo After Spray		Load JPG	☒
91	17/07/20 20:39	Photo After Spray		Load JPG	☒
92	17/07/20 20:39	Photo After Spray		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/20 15:29	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/07/20 16:44	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20007275/EQF3S2**Date:** 21/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509474
Claimant Vehicle No :	SMC7362P	Insured Vehicle No :	SLN8507L
Date of Loss:	09/07/2020	Nature of Claim:	TP
		Claim No:	0923290103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC7362P		
Make & Model:	BMW X3 SDRIVE, 2.0 20I LED SR NAV (A)	Engine No:	22265232B48B20A
Reg. Date:	19/07/2018 (Man. Year: 2018)	Chassis No:	WBATR120X0LC94222
Colour:	Brown	Odometer:	57919 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/07/2020	
Date Inspected:	14/07/2020	Inspected At: Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY , # 01-52 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER UPPER	Cut	0.00 F	*- F
3	1		*REAR BUMPER LOWER	Cut	0.00 F	*- F
4	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	*Check	0.00 F	*- F
8	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
9	1		*BOOTLID LOCK	Bent	0.00 F	*- F
10	1		*TAILGATE	Dented	0.00 F	*- F
11	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
12	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$)	0.00	0.00
------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >