

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007277/APA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100429226
Claimant
Vehicle No : SJJ1775U **Insured Vehicle No :** SKV4273G
Date of Loss: 11/07/2020 **Nature of Claim:** TP **Claim No:** 2449977617SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ1775U**
 Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A12804329
 Reg. Date: 03/09/2008 (Man. Year: 2008) Chassis No: JHMRN68408S204332
 Colour: White Odometer: 178298 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,961.76	4,196.40	2,765.36	39.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,800.00	1,950.00	52.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,711.76	5,996.40	4,715.36	44.02
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	10,711.76	4,800.00	5,911.76	55.19
+ GST 7.00/7.00% (S\$)	749.82	336.00	413.82	55.19
Nett Amount (S\$)	11,461.58	5,136.00	6,325.58	55.19
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,623.45		
Global Sum Settlement (S\$)		5,620.00		

INSPECTION

Date of Assignment: 14/07/2020
 Date Inspected: 16/07/2020 Inspected At: Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22
 Autobay
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET STOPPER	Not Necessary	60.00 FL	*- FL
2	1		*FRONT BONNET INNER LOCK	Not Necessary	185.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	357.60 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	45.80 FL	*45.80 FL
5	1		*FRONT HEADLAMPS (HID) RH	Cut	1,437.00 FL	*774.60 FL
6	1		*FRONT HEADLAMPS LOWER BRACKET RH	Not Necessary	79.80 FL	*- FL
7	1		*FRONT ENGINE UNDERCOVER	Not Necessary	159.60 FL	*- FL
8	1		*FRONT FENDER RH	Dented	497.50 FL	*497.50 FL
9	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	58.90 FL	*- FL
10	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	98.70 FL	*- FL
11	1		*FRONT FENDER INNER COWLING RH	Deformed	157.90 FL	*157.90 FL
12	1		*FRONT FENDER SUPPRESOR GARNISH RH	Not Necessary	68.70 FL	*- FL
13	1		*FRONT DOOR RH	Dented	1,456.30 FL	*960.70 FL
14	1		*FRONT ABSORBER RH	Not Necessary	519.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM RH	Not Necessary	398.70 FL	*- FL
16	1		*FRONT WHEEL HUB BEATING RH	Necessary	358.20 FL	*358.20 FL
17	1		*FRONT LOWER ARM RH	Bent	325.80 FL	*325.80 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*SET SIDESKIRT CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*FRONT RIM (RH)	Cut	700.00 FS	*450.00 FS
22	1		*SIDESKIRT RH (ACCESSORIES)	Cracked	480.00 FS	*480.00 FS
23	1		*FRONT BUMPER (ACCESSORIES)	Deformed	680.00 FS	*680.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,214.70	4,820.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,252.94	624.10
Total Parts (\$)	6,961.76	4,196.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW ,REPAIR ,RELAIN DAMAGED PARTS ,REPLACE ,BEAT AND WELD	New	1,400.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	1,400.00	800.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE /REFIT REAR INTERIOR UPHOLSTERY	New	180.00	0.00
5	LABOUR TO REMOVE /REFIT /REPLACE FRONT UNDERCARRIAGE	New	180.00	150.00
6	TO CONDUCT WIRING CHECK AND RESET HEADLAMPS TO ITS PRE-ACCIDENT CONDITION	New	120.00	30.00
7	TO PERFORM COMPUTERISED WHEEL ALIGNMENT (BEFORE AND AFTER)	New	120.00	80.00
8	TO REMOVE AND REFIT DOOR FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			3,750.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >