

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924 INV No. AC2005025

INV Date 17/07/2020

Reference CS/AGI20007279/Usf3n2

Code AG

PROFESSIONAL SERVICE FEE

Vehicle No. SDQ 3683Y

Insured Veh. SJT 3274H

Claim No. C10006718

Policy No.

Accident Date 13/07/2020

Inspection Date 15/07/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R						
	Affiliated to Federation Internationale Des Experts En Automobile						
AUT	UTO & GENERAL INSURANCE (S) PL Ref : CS/AGI20007279/Usf3n2						
190 SINC	(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date: 17-07-2020				
			Code: AGI				
1.	I		:- THIRD PARTY CLAIM	222224			
	Insured Veh.	SJT 3274H	Veh. Inspected	SDQ 3683Y			
	Policy No. Coverage (\$)			0.00			
	Claim No.	C10006718	Excess (\$)	0.00			
	Assign From	IVY RATILLA	Assign Date	14/07/2020			
2.	2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS (A)	c.c	1496			
	Engine No.	HIDDEN	Year of Reg.	2019			
	Chassis No. MR2B23F3X01165675 Colour		Colour	SILVER			
	Odometer	17659	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Conditi	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm			
	L/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm			
	R/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm			
	L/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm			
4.		Description	on of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	FRONT PORTION.				
	DAMAGES SEE D	ETAILS.					
5.	•	General	I Information				
	Accident Date	13/07/2020	Inspection Date	15/07/2020			
	Survey held at	1 DEFU LANE 6 SINGAPORE 5	39365				
	Repairer TAN LIM MOTOR PTE LTD						
5a.	•	Re	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	b. Estimate Days of Repair						

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 3683Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	486.00	486.00
1	N/S FRONT BUMPER SIDE RETAINER	CRACKED	62.00	62.00
8	FRONT BUMPER FASTENER CLIP @\$5.00	NECESSARY	40.00	40.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	282.50	-
1	N/S FRONT BUMPER DAYLIGHT	NOT NECESSARY	398.70	-
1	N/S FRONT BUMPER LOWER SPOILER	NO SUCH PARTS	330.00	-
1	N/S FRONT FENDER	BUCKLED	511.90	511.90
1	N/S FRONT FENDER INNER COWLING	TORN	168.10	168.10
1	N/S FRONT SHOCK ABSORBER	NOT NECESSARY	511.00	-
1	N/S FRONT KNUCKLE ARM	NOT NECESSARY	495.00	-
1	N/S FRONT WHEEL BEARING	NOT NECESSARY	158.90	-
1	N/S FRONT WHEEL HUB	NOT NECESSARY	210.00	-
1	N/S FRONT ANTI-ROLL BAR LINK	NOT NECESSARY	182.00	-
1	N/S FRONT BUMPER FOG LAMP	NOT NECESSARY	250.00	-
1	N/S FRONT BUMPER FOG LAMP COVER	SCRATCHED	135.00	135.00
1	N/S HEADLAMP	CRACKED	446.00	446.00
	LESS 25% DISCOUNT		-1,166.78	-462.25
			3,500.32	1,386.75
	SPECIAL NETT ITEMS			
1	N/S FRONT WHEEL RIM (SN)	NOT NECESSARY	350.00	-
1	N/S FRONT WHEEL TYRE (SN)	NOT NECESSARY	300.00	-
			650.00	-
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS,REMOVE AND RENEWAL OF THE NECESSARY PARTS,TO PERFORM FINAL CHECKING AND TESTING.	NOT NECESSARY	150.00	-

Report Ref No. CS/AGI20007279/Usf3n2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,746.75

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER OF TYRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	30.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		800.00	450.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	800.00
			2,440.00	1,360.00
	GRAND TOTAL		6,590.32	2,746.75

Report Ref No. CS/AGI20007279/Usf3n2

CHUA KANG SENG

Licensed Appraiser

Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDQ 3683Y

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDQ 3683Y

RE-INSPECTION











