

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007281/AEA3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100383870

Claimant
Vehicle No : SKC5820X **Insured Vehicle No :** SKP2937U

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: 1517748822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC5820X**
 Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGBU331777
 Reg. Date: 13/09/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU271006
 Colour: Blue Odometer: 131587 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,851.36	1,101.20	750.16	40.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	760.00	750.00	49.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,361.36	1,861.20	1,500.16	44.63
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,361.36	1,500.00	1,861.36	55.38
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,907.45		

INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020 Inspected At:

Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90
 Autobay@Kaki
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	559.40 FL	*559.40 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	54.00 FL	*54.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Necessary	54.00 FL	*54.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Deformed	494.80 FL	*345.80 FL
5	1		*KEYLESS SENSOR	Not Necessary	185.60 FL	*- FL
6	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	290.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Cut	75.80 FL	*75.80 FL
8	1		*REAR BUMPER REFLECTOR LH	Not Necessary	75.80 FL	*- FL
9	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR END PANEL GARNISH	Not Necessary	99.80 FL	*- FL
11	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
12	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
13	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
14	8		*REAR END PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,229.20	1,319.00
- List Item Discount on L Items 20.00/20.00% (\$)	377.84	217.80
Total Parts (\$)	1,851.36	1,101.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	600.00	300.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	400.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	60.00	30.00
Gross Labour Cost (\$)			1,510.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >