

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007283/KDA3Q2

**Date:** 16/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900194020

**Claimant**  
**Vehicle No :** SKT5041M **Insured Vehicle No :** SMP7904H

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: 2979335000SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKT5041M</b>		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B3521557
Reg. Date:	11/06/2015 (Man. Year: 2015)	Chassis No:	RU11021541
Colour:	Metallic Silver	Odometer:	84736 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,741.72	2,589.45	152.27	5.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,280.00	390.00	23.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,411.72</b>	<b>3,869.45</b>	<b>542.27</b>	<b>12.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>(S\$)</b>	4,411.72	3,050.00	1,361.72	30.87
<b>+ GST 7.00/7.00% (S\$)</b>	308.82	213.50	95.32	30.87
<b>Nett Amount (S\$)</b>	<b>4,720.54</b>	<b>3,263.50</b>	<b>1,457.04</b>	<b>30.87</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,765.50</b>		

### INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 15/07/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun  
Industrial Park A  
Singapore 768761

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	518.60 FL	*518.60 FL
2	1		*REAR BUMPER RH SIDE PAD	Dented	195.00 FL	*195.00 FL
3	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
4	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	43.80 FL	*43.80 FL
6	1		*TAILGATE INNER LOCK	Dented	143.80 FL	*143.80 FL
7	1		*TAILGATE INNER RUBBER (50%)	Distorted / Dented	78.80 FS	*49.25 FS
8	1		*TAILGATE INNER TRIM BOARD	Serviceable	153.40 FL	*- FL
9	1		*TAILGATE RH REFLECTOR	Cut	298.10 FL	*298.10 FL
10	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	151.80 FL	*151.80 FL
11	1		*RH TAILLAMP	Cut	399.85 FL	*399.85 FL
12	1		*REVERSE SENSOR	Dented / Shorted	200.00 FS	*200.00 FS
13	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,347.45</b>	<b>3,164.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	605.73	575.05
<b>Total Parts (S\$)</b>	<b>2,741.72</b>	<b>2,589.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPE ASSY ,REVERSE SENSOR ,REAR WIPER ASSY ,THIRD BRAKE LIGHT ,TOP SPOILER ,TAILGATE ASSY ,LOCK ASSY ,TO KNOCK & REPAIR REAR END PANEL & REALIGN THE SAME	New	750.00	500.00
3	REMOVE & REFIX REAR FENDER GARNISH ,SEAT ,ETC	New	60.00	60.00
4	PUTTY & RESPRAY ON REAR END PANEL ,REAR BUMPER SIDES ,TAILGATE	New	650.00	520.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	60.00	50.00
6	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,670.00</b>	<b>1,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >