

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007285/UGS3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SGY2384P	Insured Vehicle No :	GBJ7796P
Date of Loss:	07/07/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001325

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY2384P		
Make & Model:	HONDA CIVIC, 1.8 L (A)	Engine No:	R18A12039426
Reg. Date:	20/09/2007 (Man. Year: 2007)	Chassis No:	JHMF16307S218430
Colour:	White	Odometer:	168756 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,070.40	1,295.24	3,775.16	74.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	620.00	1,200.00	65.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,890.40	1,915.24	4,975.16	72.20
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,890.40	1,500.00	5,390.40	78.23
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,987.45		

INSPECTION

Date of Assignment:	13/07/2020	
Date Inspected:	13/07/2020 Inspected At:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt Singapore 428586
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2020)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY2384P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,072.50 FL	*- FL
2	1		*BONNET INNER LOCK (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*BONNET INSULATOR (NPA)	Not Necessary	0.00 FL	*- FL
4	2		*BONNET RUBBER STOPPER	Not Necessary	84.00 FL	*- FL
5	1		*FRONT CENTRE GRILLE CHROME ASSY (CRACKED)	Not Consistent With The Impact	498.00 FL	*- FL
6	1		*FRONT CENTRE GRILLE CHROME BADGE	Not Necessary	72.00 FL	*- FL
7	1		*FRONT BUMPER	Cut / Torn	1,150.00 FL	*638.00 FL
8	1		*FRONT BUMPER LOWER COVER	Not Necessary	275.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINERS	O/S Cracked	98.00 FL	*25.20 FL
10	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	157.50 FL	*- FL
11	1		*FRONT BUMPER LED DAYLIGHT RHS	Not Necessary	392.00 FL	*- FL
12	1		*FRONT BUMPER LED DAYLIGHT GARNISH RHS	Not Necessary	224.00 FL	*- FL
13	1		*RHS FRONT FENDER	Repair	671.80 FL	*- FL
14	1		*RHS FRONT FENDER INNER SPLASH SHIELD	Not Necessary	214.00 FL	*- FL
15	1		*RHS HEADLAMP	Cracked / Scratched	985.20 FL	*912.10 FL
16	1		*RHS HEADLAMP SUPPORT BRACKET	Not Necessary	119.00 FL	*- FL
17	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*35.00 FS
18	1		*FRONT LICENSE PLATE (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*FRONT LICENSE PLATE GARNISH (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*SET FRONT CENTRE RADIATOR GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
21	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
22	1		*SET BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,273.00	1,610.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,202.60	315.06
Total Parts (\$\$)	5,070.40	1,295.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	800.00	200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	750.00	400.00
3	TO REMOVE,CHECK /REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	150.00	20.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,820.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >