

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20007286/ARA3Q2  
**Date:** 29/03/2021

### REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100235119   |
| <b>Claimant Vehicle No :</b> | SMQ4121P                             | <b>Insured Vehicle No :</b> | GBB9702P     |
| Date of Loss:                | 13/07/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 6803194114SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMQ4121P</b>                   | Engine No:  | G4FGKU473257      |
| Make & Model:               | HYUNDAI AD AVANTE, 1.6 GLS S (A)  | Chassis No: | KMHD841CMLU009032 |
| Reg. Date:                  | 15/11/2019 (Man. Year: 2019)      | Odometer:   | 38574 km          |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/65 R16   | Rear Tyre Size:  | 205/65 R16   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                     | Repairer's                   | Adjuster's      | Difference      | Diff %       |
|----------------------------------------------------|------------------------------|-----------------|-----------------|--------------|
| Parts                                              | 8,732.88                     | 4,671.76        | 4,061.12        | 46.50        |
| Miscellaneous Items                                | 0.00                         | 0.00            | 0.00            |              |
| Labour                                             | 4,370.00                     | 1,640.00        | 2,730.00        | 62.47        |
| Paintwork Labour                                   | 0.00                         | 0.00            | 0.00            |              |
| Towing                                             | 0.00                         | 0.00            | 0.00            |              |
| <b>Gross Total (\$\$)</b>                          | <b>13,102.88</b>             | <b>6,311.76</b> | <b>6,791.12</b> | <b>51.83</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b>                     | <b>917.20</b>                | <b>441.82</b>   | <b>475.38</b>   | <b>51.83</b> |
| <b>Nett Amount (\$\$)</b>                          | <b>14,020.08</b>             | <b>6,753.58</b> | <b>7,266.50</b> | <b>51.83</b> |
| <b>+ Loss of Use (4.0 x \$S\$60.00/day) (\$\$)</b> |                              | <b>240.00</b>   |                 |              |
|                                                    | <b>Nett Liability (\$\$)</b> | <b>6,993.58</b> |                 |              |

### INSPECTION

|                             |            |               |                                                                                       |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------------------|
| Date of Assignment:         | 15/07/2020 |               |                                                                                       |
| Date Inspected:             | 15/07/2020 | Inspected At: | Cas Garage Pte Ltd (HQ)<br>No.1, Kaki Bukit Ave 6, #02-22 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                                       |

**Adjuster:** ADRIAN LING

**Manager:** Jaslin Kok Chin Yi

3/29/2021

Adjuster Report

*any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOTLID                      | Dented        | 1,853.60 FL | *1,782.00 FL |
| 2   | 1   |          | *REAR BOOTLID INNER LOCK           | Not Necessary | 145.70 FL   | *- FL        |
| 3   | 1   |          | *REAR BOOTLID SMARTKEY ANTENNA     | Not Necessary | 198.70 FL   | *- FL        |
| 4   | 1   |          | *REAR BOOTLID INNER TRIM           | Not Necessary | 195.80 FL   | *- FL        |
| 5   | 1   |          | *REAR BOOTLID LATCH                | Not Necessary | 38.50 FL    | *- FL        |
| 6   | 1   |          | *REAR BOOTLID LOGO                 | Necessary     | 79.60 FL    | *79.60 FL    |
| 7   | 1   |          | *REAR BOOTLID AVANTE EMBLEM        | Necessary     | 95.20 FL    | *95.20 FL    |
| 8   | 1   |          | *REAR BOOTLID S EMBLEM             | Necessary     | 82.30 FL    | *82.30 FL    |
| 9   | 1   |          | *REAR BOOTLID WEATHERSTRIP         | Not Necessary | 145.60 FL   | *- FL        |
| 10  | 2   |          | *REAR BOOTLID LAMPS                | Not Necessary | 1,304.60 FL | *- FL        |
| 11  | 1   |          | *END PANEL                         | Repair        | 657.80 FL   | *- FL        |
| 12  | 1   |          | *END PANEL TOP GARNISH             | Cracked       | 175.90 FL   | *175.90 FL   |
| 13  | 1   |          | *END PANEL SMARTKEY ANTENNA        | Cracked       | 178.90 FL   | *178.90 FL   |
| 14  | 1   |          | *TAILAMPS                          | O/S Cracked   | 1,691.20 FL | *845.60 FL   |
| 15  | 2   |          | *TAILAMPS INNER SEALER             | Not Necessary | 80.00 FL    | *- FL        |
| 16  | 1   |          | *REAR BUMPER                       | Deformed      | 598.70 FL   | *598.70 FL   |
| 17  | 1   |          | *REAR BUMPER LOWER                 | Deformed      | 496.30 FL   | *496.30 FL   |
| 18  | 2   |          | *REAR BUMPER RETAINERS             | Cracked       | 171.80 FL   | *171.80 FL   |
| 19  | 1   |          | *REAR BUMPER REFLECTOR             | O/S Cracked   | 611.40 FL   | *305.70 FL   |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT         | Cracked       | 489.30 FL   | *392.00 FL   |
| 21  | 2   |          | *REAR REINFORCEMENT BRACKETS (TOP) | Not Necessary | 137.80 FL   | *- FL        |
| 22  | 3   |          | *REINFORCEMENT BRACKETS (BOTTOM)   | Cracked       | 230.40 FL   | *230.40 FL   |
| 23  | 2   |          | *REINFORCEMENT BRACKETS METAL      | Not Necessary | 397.40 FL   | *- FL        |
| 24  | 2   |          | *REAR BUMPER LOWER COVER           | Not Necessary | 291.80 FL   | *- FL        |
| 25  | 1   |          | *REAR NUMBER PLATE GARNISH         | Deformed      | 42.80 FL    | *42.80 FL    |
| 26  | 1   |          | *SET REAR NUMBER PLATE WITH CASING | Bent          | 50.00 FS    | *50.00 FS    |
| 27  | 1   |          | *SET REAR BUMPER CLIPS             | Necessary     | 30.00 FS    | *30.00 FS    |
| 28  | 1   |          | *SET END PANEL TOP GARNISH CLIPS   | Necessary     | 30.00 FS    | *10.00 FS    |
| 29  | 1   |          | *SET REAR BUMPER INNER TRIM CLIPS  | Not Necessary | 30.00 FS    | *- FS        |
| 30  | 1   |          | *SET REAR BUMPER LOWER COVER CLIPS | Not Necessary | 30.00 FS    | *- FS        |
| 31  | 1   |          | *SET REAR REVERSE SENSOR           | Damaged       | 250.00 FS   | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |                  |                 |
|-----------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                             | <b>10,811.10</b> | <b>5,767.20</b> |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 2,078.22         | 1,095.44        |
| <b>Total Parts (\$\$)</b>                           | <b>8,732.88</b>  | <b>4,671.76</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                               | Lab.Type | Repairer's      | Amount          |
|-------------------------|---------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                                                           |          |                 |                 |
| 1                       | TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS | New      | 1,600.00        | 600.00          |
| 2                       | TO RESPRAY AFFECTED AREAS                                                 | New      | 1,600.00        | 750.00          |
| 3                       | TO TUFFCOAT AFFECTED AREA                                                 | New      | 200.00          | 50.00           |
| 4                       | TO CONDUCT WIRING CHECK ON THE REAR TAILLAMPS                             | New      | 150.00          | 30.00           |
| 5                       | TO REMOVE /REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING             | New      | 180.00          | 50.00           |
| 6                       | TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY                                  | New      | 120.00          | 50.00           |
| 7                       | TO CONDUCT WATER LEAKAGE TEST                                             | New      | 120.00          | 0.00            |
| 8                       | TO APPLY UNDERCOATING TO THE AFFECTED AREAS                               | New      | 250.00          | 50.00           |
| 9                       | TO REMOVE /REFIT AND REPLACE BOOTLID MECHANISM                            | New      | 150.00          | 60.00           |
| Gross Labour Cost (S\$) |                                                                           |          | <b>4,370.00</b> | <b>1,640.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >