

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 206X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	582.70	582.70
1	REAR BUMPER REINFORCEMENT	BENT	386.30	386.30
1	REAR BUMPER RETAINER LH	CRACKED	149.90	149.90
1	REAR BUMPER RETAINER (SMALL) LH	CRACKED	68.80	68.80
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	98.90	-
1	REAR PANEL	NOT NECESSARY	630.40	-
1	REAR PANEL TRIM	NOT NECESSARY	232.20	-
1	TAIL LAMP LH	NOT NECESSARY	395.70	-
	LESS 25% DISCOUNT		-636.23	-296.93
			1,908.67	890.77
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
1	SET REAR BUMPER STICKER (SN)	NECESSARY	195.00	160.00
2	'L' PLATE BRACKET (SN)	NECESSARY	70.00	50.00
1	SET REAR PANEL TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
			335.00	250.00
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	TO REPLACE STICKER .		100.00	30.00
	TO SPRAY UNDERSEAL .	NOT NECESSARY	100.00	-
	(REAR) TO SPRAY PAINTING.		800.00	400.00
	TO REMOVE AND REFIT INNER TRIM .	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS.		800.00	300.00
			-	-
			-	-
			-	-
			1,950.00	760.00
	GRAND TOTAL		4,193.67	1,900.77

Report Ref No. CS/AGI20007287/Aqf3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 1,900.77

Report Ref No. CS/AGI20007287/Aqf3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.