

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007289/KEA3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900077367

Claimant
Vehicle No : SLG9524S **Insured Vehicle No :** SMK7171G

Date of Loss: 11/07/2020 Nature of Claim: TP Claim No: 4754269235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG9524S		
Make & Model:	TOYOTA AQUA, 1.5 E 1.5 SA (A)	Engine No:	1NZ8017977
Reg. Date:	19/10/2016 (Man. Year: 2016)	Chassis No:	NHP106531199
Colour:	White	Odometer:	253134 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	SUNWIDE 7 mm	Rear Left Side:	SUNWIDE 8 mm
Front Right Side:	SUNWIDE 7 mm	Rear Right Side:	SUNWIDE 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,102.27	3,661.65	440.62	10.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	1,230.00	290.00	19.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,622.27	4,891.65	730.62	13.00
Approved Total (Overridden) (\$\$)		3,900.00		
(\$\$)	5,622.27	3,900.00	1,722.27	30.63
+ GST 7.00/7.00% (\$\$)	393.56	273.00	120.56	30.63
Nett Amount (\$\$)	6,015.83	4,173.00	1,842.83	30.63
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
Nett Liability (\$\$)		4,533.00		

INSPECTION

Date of Assignment: 15/07/2020

Date Inspected: 15/07/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Mtg Cracked	1,374.30 FL	*1,374.30 FL
2	1		*FRONT BUMPER LAMP LH	Cracked	341.20 FL	*341.20 FL
3	1		*FRONT BUMPER	Buckled	1,124.50 FL	*1,124.50 FL
4	1		*FRONT BUMPER SIDE BRACKET LH	Distorted	67.60 FL	*67.60 FL
5	8		*FRONT BUMPER CLIPS	Necessary	41.60 FL	*41.60 FL
6	1		*FRONT FENDER LH	Buckled	477.70 FL	*477.70 FL
7	1		*FRONT FENDER HYBRID EMBLEM	Necessary	48.30 FL	*48.30 FL
8	1		*FRONT FENDER INNER LINER LH	Serviceable	216.90 FL	*- FL
9	10		*FRONT FENDER INNER LINER CLIPS LH	Not Necessary	55.00 FL	*- FL
10	1		*FRONT WHEEL RIM LH (LOCAL PURCHASE)	Bent	298.35 FS	*180.00 FS
11	1		*FRONT WHEEL CAP LH	Missing	218.60 FL	*218.60 FL
12	1		*FRONT WHEEL RIM RH (LOCAL PURCHASE)	Dented	298.35 FS	*180.00 FS
13	1		*FRONT WHEEL CAP RH	Cracked	218.60 FL	*218.60 FL
14	1		*FRONT LOWER ARM RH	Distorted	457.80 FL	*457.80 FL
15	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
16	1		*FRONT TYRE TUBE VALVE LH	Necessary	12.00 FS	*12.00 FS
17	1		*FRONT TYRE TUBE VALVE RH	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,262.80	4,754.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,160.53	1,092.55
Total Parts (\$\$)	4,102.27	3,661.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	500.00	400.00
2	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX FRONT BOTH WHEEL RIM ,FRONT BOTH TYRES,FRONT LOWER ARM RH & ETC	New	180.00	150.00
3	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER ,LH FRONT DOOR LH & ETC	New	700.00	600.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
5	TO WHEEL ALIGNMENT & BALANCING	New	60.00	60.00
Gross Labour Cost (S\$)			1,520.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >