

ASS. REC. BY:

REF:

AIG/ 20007289/1Kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 9524S

Yr Regn:

10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy A908

c.c

1496

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

253134

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

N14P106.531199

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

1P5/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Sunwide

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

11/7/20

D.O.I.

15/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/7 11/20 @ 3900d Carbin

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

F. P. M.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 14.07.2020
 Vehicle No: SLG9524S
 Model: TOYOTA AQUA HYBRID 1.5S
 Chassis: NHP106531199-2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMK7171G
 Date of Accident: 11.07.2020

ESTIMATE

Not Notified
 11 Day @ 3900/-
 5 days Presurvey After Painting

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	my cm	\$1,374.30
2	FRONT BUMPER LAMP LH	1	cm	\$341.20
3	FRONT BUMPER	1	Ben	\$1,124.50
4	FRONT BUMPER SIDE BRACKET LH	1	DI	\$67.60
5	FRONT BUMPER CLIPS	8	\$5.20	Ben \$41.60
6	FRONT FENDER LH	1	Ben	\$477.70
7	FRONT FENDER 'HYBRID' EMBLEM	1	Ben	\$48.30
8	FRONT FENDER INNER LINER LH	1	Ben	\$216.90
9	FRONT FENDER INNER LINER CLIPS LH	10	\$5.50	Ben \$55.00
10	FRONT WHEEL RIM LH	1	1805w L.F	Ben \$397.80
11	FRONT WHEEL CAP LH	1	Ben	\$218.60
12	FRONT WHEEL RIM RH	1	1805w	Ben \$397.80
13	FRONT WHEEL CAP RH	1	cm	\$218.60
14	FRONT LOWER ARM RH	1	DI	\$457.80
15	FRONT DOOR LH	1		REPAIR
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer				
SUB TOTAL				\$5,437.70
LESS 25%				-\$1,359.43
PARTS TOTAL				\$4,078.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT TYRE TUBE VALVE LH	1	Ben	\$12.00
2	FRONT TYRE TUBE VALVE RH	1	Ben	\$12.00
S/N TOTAL				\$24.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$500.00 400/-

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT BOTH WHEEL RIM, FRONT BOTH TYRES, FRONT LOWER ARM RH & ETC.

\$180.00 150/-

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH & ETC.

\$700.00 600/-

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.07.2020
Vehicle No: SLG9524S
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106531199-2016
Reg.Year: 2016

Third Party Insurer:
Third Party Veh No: SMK7171G
Date of Accident: 11.07.2020

TO CHECK WIRING & ELECTRICAL SYSTEM.

20/ \$80.00

TO WHEEL ALIGNMENT & BALANCING.

\$60.00 ✓

LABOUR TOTAL \$1,520.00

TingAn

TOTAL

\$5,622.28

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

