

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007291/KDS3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800077694

**Claimant**  
**Vehicle No :** SDW5168Z **Insured Vehicle No :** SJH1238P

Date of Loss: 12/07/2020 Nature of Claim: TP Claim No: 3250373502SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDW5168Z</b>		
Make & Model:	MERCEDES-BENZ S400L, 3.0 (A)	Engine No:	27682430121807
Reg. Date:	16/02/2015 (Man. Year: 2014)	Chassis No:	WDD2221652A119635
Colour:	Metallic Black	Odometer:	176348 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	275/40R19
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	45,396.00	21,843.20	23,552.80	51.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,930.00	1,770.00	47.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>49,096.00</b>	<b>23,773.20</b>	<b>25,322.80</b>	<b>51.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>19,000.00</b>		
<b>(S\$)</b>	49,096.00	19,000.00	30,096.00	61.30
<b>+ GST 7.00/7.00% (S\$)</b>	3,436.72	1,330.00	2,106.72	61.30
<b>Nett Amount (S\$)</b>	<b>52,532.72</b>	<b>20,330.00</b>	<b>32,202.72</b>	<b>61.30</b>
<b>+ Car Rental (9.0 x S\$180.00/day + 7.00% GST) (S\$)</b>		1,733.40		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>22,065.40</b>		
<b>Global Sum Settlement (S\$)</b>		<b>22,000.00</b>		

### INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 15/07/2020 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)  
176 Sin Ming Drive #01-15, Sin Ming  
AutoCare  
Singapore 575721

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	3,800.00 FL	*3,150.00 FL
2	1		*BONNET INSULATOR	Serviceable	250.00 FL	*- FL
3	1		*BONNET COVER	Serviceable	350.00 FL	*- FL
4	2		*FENDER	Bent	2,530.00 FL	*2,530.00 FL
5	1		*WHEEL ARCH COVER LH	Distorted	270.00 FL	*270.00 FL
6	1		*FENDER LH INTERMEDIATE LAYER FRONT	Serviceable	30.00 FL	*- FL
7	1		*FRONT BUMPER	Bent	2,100.00 FL	*2,019.00 FL
8	1		*FRONT BUMPER TOWING COVER	Serviceable	60.00 FL	*- FL
9	1		*FRONT BUMPER IMPACT ABSORBER	Cracked	270.00 FL	*270.00 FL
10	2		*FRONT BUMPER BASIC CARRIER LH & RH	Serviceable	350.00 FL	*- FL
11	1		*FRONT BUMPER CENTER GRILLE	Serviceable	110.00 FL	*- FL
12	1		*FRONT BUMPER SPOILER BOTTOM	Serviceable	300.00 FL	*- FL
13	1		*FRONT BUMPER COVER LH INNER	Distorted	130.00 FL	*130.00 FL
14	1		*FRONT BUMPER COVER LH OUTER	Cracked	160.00 FL	*160.00 FL
15	1		*FRONT BUMPER TRIM STRIP COVER LH	Serviceable	140.00 FL	*- FL
16	1		*FRONT BUMPER CROSS MEMBER	Bent	800.00 FL	*719.00 FL
17	15		*FRONT BUMPER RIVET	Necessary	120.00 FL	*120.00 FL
18	1		*FRONT BUMPER SENSOR	Serviceable	200.00 FL	*- FL
19	1		*HEAD LAMP LH	Broken	7,000.00 FL	*6,280.00 FL
20	1		*HEAD LAMP SEALING FRAME LH	Serviceable	120.00 FL	*- FL
21	1		*HEAD LAMP CONTROL UNIT LH	Serviceable	1,000.00 FL	*- FL
22	1		*HEAD LAMP LH FRAME	Repair	400.00 FL	*- FL
23	1		*STEERING KNUCKLE LH	Necessary	2,000.00 FL	*1,820.00 FL
24	1		*STEERING KNUCKLE RH	Serviceable	2,000.00 FL	*- FL
25	1		*TRANSV CONTROL ARM RH	Serviceable	1,500.00 FL	*- FL
26	1		*TRANSV CONTROL ARM LH	Bent	1,500.00 FL	*1,280.00 FL
27	1		*SPRING LINK RH	Serviceable	1,300.00 FL	*- FL
28	1		*SPRING LINK LH	Serviceable	1,300.00 FL	*- FL
29	1		*STRUT ROD LH	Serviceable	800.00 FL	*- FL
30	1		*STRUT ROD RH	Serviceable	800.00 FL	*- FL
31	1		*WHEEL BEARING RH	Not Necessary	800.00 FL	*- FL
32	1		*WHEEL BEARING LH	Not Necessary	800.00 FL	*- FL
33	1		*KNUCKLE ARM TIE ROD	Serviceable	200.00 FL	*- FL
34	1		*KNUCKLE ARM TIE ROD END	Serviceable	350.00 FL	*- FL
35	1		*AIR SUSPENSION STRUT LH	Bent	5,000.00 FL	*4,250.00 FL
36	1		*AIR SUSPENSION STRUT RH	Serviceable	5,000.00 FL	*- FL
37	2		*REPAIR KIT LH & RH	Serviceable	600.00 FL	*- FL
38	1		*NUMBER PLATE & HOLDER	Dented	50.00 FS	*45.00 FS
39	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS
40	1		*CERAMIC COATING	Not Necessary	800.00 FS	*- FS
41	1		*FRONT SPORT RIMS LH	Dented	1,500.00 FS	*1,100.00 FS
42	1		*FRONT SPORT RIMS RH	Serviceable	1,500.00 FS	*- FS
43	1		*FRONT TYRE LH	Serviceable	750.00 FS	*- FS
44	1		*FRONT TYRE RH	Serviceable	750.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>49,840.00</b>	<b>24,143.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>4,444.00</b>	<b>2,299.80</b>
<b>Total Parts (\$\$)</b>	<b>45,396.00</b>	<b>21,843.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,500.00	700.00
2	TO REMOVE ,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	0.00
3	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	200.00	30.00
4	TO REMOVE & REFIT ALL SENSOR	New	100.00	60.00
5	TO REMOVE ,RENEW & REFIT FRONT LH & RH TYRE	New	100.00	20.00
6	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	200.00	0.00
7	TO REMOVE & REFIT FRONT RH & LH UNDERCARRIAGE	New	500.00	240.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	880.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,700.00</b>	<b>1,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >