

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007296/KDS3Q2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419848
Claimant
Vehicle No : SKX4997R **Insured Vehicle No :** SJZ1437L
Date of Loss: 11/07/2020 **Nature of Claim:** TP **Claim No:** 3744172397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX4997R**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4024886
 Reg. Date: 16/12/2015 (Man. Year: 2015) Chassis No: RU11104883
 Colour: Metallic Silver Odometer: 95950 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Linglong 8 mm Rear Left Side: Linglong 8 mm
 Front Right Side: Linglong 8 mm Rear Right Side: Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,382.40	1,382.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	200.00	330.00	62.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,912.40	1,582.40	330.00	17.26
+ GST 7.00/7.00% (S\$)	133.87	110.77	23.10	17.26
Nett Amount (S\$)	2,046.27	1,693.17	353.10	17.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 14/07/2020
 Date Inspected: 14/07/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
 6 Kung Chong Road
 Singapore 159143
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ARCH EXTENSION COVER RH	Dented / Bent	192.00 FL	*192.00 FL
2	1		*REAR ALLOY RIM RH	Dented	1,521.00 FL	*1,521.00 FL
3	1		*REAR SIDE BUMPER RH (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR TYRE TUBE VALVE RH	Necessary	12.00 FS	*12.00 FS
				Sub Total (\$)	1,725.00	1,725.00
				- List Item Discount on L Items 20.00/20.00% (\$)	342.60	342.60
				Total Parts (\$)	1,382.40	1,382.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	250.00	80.00
2	LABOUR CHARGES TO REMOVE ,REFIX ,REPLACE REAR ALLOY RIM RH & ETC	New	80.00	20.00
3	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC	New	200.00	100.00
Gross Labour Cost (\$)			530.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >