

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007297/T1PA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBJ1405H	Insured Vehicle No :	SH6244G
Date of Loss: 11/07/2020	Nature of Claim: TP	Claim No: MCT20070146

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ1405H		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2833668
Reg. Date:	08/01/2019 (Man. Year: 2018)	Chassis No:	JTFHT02P400246707
Colour:	Silver	Odometer:	40336 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/ R15	Rear Tyre Size:	195/ R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,386.82	1,423.99	1,962.83	57.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	760.00	500.00	39.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	4,646.82	2,183.99	2,462.83	53.00
Approved Total (Overridden) (\$)		1,750.00		
(\$)	4,646.82	1,750.00	2,896.82	62.34
+ GST 7.00/7.00% (\$)	325.28	122.50	202.78	62.34
Nett Amount (\$)	4,972.10	1,872.50	3,099.60	62.34
+ Car Rental (3.0 x S\$80.00/day) (\$)		240.00		
+ Doc/Search Fee (\$)		36.45		
Nett Liability (\$)		2,148.95		
Global Sum Settlement (\$)		2,100.00		

INSPECTION

Date of Assignment:	14/07/2020	
Date Inspected:	15/07/2020 Inspected At:	Teamwork Garage Pte Ltd (HQ)
		53 Ubi Ave 1 #01-24, Paya Ubi
		Industrial Park
		Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1405H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	898.66 FL	*898.66 FL
2	1		*FRONT GRILLE UPPER	Not Necessary	428.30 FL	*- FL
3	1		*FRONT GRILLE LOWER	Not Necessary	439.81 FL	*- FL
4	1		*FRONT EMBLEM	Not Necessary	121.43 FL	*- FL
5	1		*FRONT LH HEADLAMP	Cut	1,429.50 FL	*1,000.00 FL
6	1		*FRONT LH HEADLAMP BRACKET	Not Necessary	121.20 FL	*- FL
7	1		*FRONT BUMPER	Repair	645.84 FL	*- FL
8	1		*FRONT BUMPER BRACKET	Not Necessary	182.10 FL	*- FL
9	1		*FRONT BUMPER GRILLE LH	Not Necessary	182.25 FL	*- FL
10	1		*SET FRONT BUMPER CLIP	Not Necessary	30.00 FS	*- FS
11	1		*SET FRONT GRILLE CLIP	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,499.09	1,898.66
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,112.27	474.67
Total Parts (\$\$)	3,386.82	1,423.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	PANEL BEATING AND RENEW PARTS ON AFFECTED AREAS	New	500.00	300.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			1,260.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >