



India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
Singapore 409711

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

Vehicle number	GBJ1405H
Make / Model	TOYOTA/HIACE VAN
Chassis number	JTFH02P400246707
Accident date	11 July 2020
Reference	

Qty	Particulars	Unit Price - SGD \$
-----	-------------	---------------------

PARTS REPLACEMENT - LIST ITEMS

- | | | |
|---|---------------------------|-------------|
| 1 | FRONT PANEL | 898.66 del |
| 1 | FRONT GRILLE UPPER | 428.30x |
| 1 | FRONT GRILLE LOWER | 439.81x |
| 1 | FRONT EMBLEM | 121.43x |
| 1 | FRONT LH HEADLAMP | 1429.50 cut |
| 1 | FRONT LH HEADLAMP BRACKET | 121.20 x |
| 1 | FRONT BUMPER | 645.84 Rs |
| 2 | FRONT BUMPER BRACKET | 182.10 x |
| 1 | FRONT BUMPER GRILLE LH | 182.25 x |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Less 25 %
Subtotal

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- | | | |
|-------|-------------------|---------|
| 1 SET | FRONT BUMPER CLIP | 30.00 x |
| 1 SET | FRONT GRILLE CIIP | 20.00 x |

Subtotal

Balance C/F

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

- | | | |
|---|---|-------------|
| 1 | CHECK FRONT WIRING AND LIGHTNING SYSTEM | 60.00 20- |
| 2 | PANEL BEATING AND RENEW PARTS ON AFFECTED AREAS | 500.00 300. |
| 3 | SPRAY PAINTING ON AFFECTED AREAS | 600.00 400. |
| 4 | APPLY ANTI RUST ON AFFECTED AREAS | 100.00 30 |

Subtotal

Grand total

Tan Kah 92445747
WP' humpson
Resurvey after repair.

15/7/20 @ 1pm 3 days
tan Kah 92445747