

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007298/AGA3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMA4912H	Insured Vehicle No :	SHA5992D
Date of Loss: 13/07/2020	Nature of Claim: TP	Claim No: MCT20070164

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4912H		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0B82210
Reg. Date:	11/06/2018 (Man. Year: 2018)	Chassis No:	JTDZS3EU10J027944
Colour:	Green	Odometer:	180865 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,294.49	2,988.50	1,305.99	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,130.00	640.00	36.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,064.49	4,118.50	1,945.99	32.09
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	6,064.49	3,300.00	2,764.49	45.58
+ GST 7.00/7.00% (\$\$)	424.51	231.00	193.51	45.58
Nett Amount (\$\$)	6,489.00	3,531.00	2,958.00	45.58
+ Car Rental (6.0 x S\$79.95/day) (\$\$)		479.70		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,018.15		

INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 20/07/2020 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA4912H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	523.90 FL	*523.90 FL
2	1	*REAR BUMPER LOWER COVER	Cracked	179.00 FL	*179.00 FL
3	1	*REAR BUMPER LOWER SPOILER	Deformed	721.00 FL	*721.00 FL
4	1	*REAR BUMPER REINFORCEMENT	Dented	350.50 FL	*350.50 FL
5	2	*REAR BUMPER REINFORCEMENT BRACKET L/R	Bent	397.40 FL	*397.40 FL
6	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	196.00 FL	*196.00 FL
7	1	*REAR END PANEL	Repair	781.45 FL	*- FL
8	1	*REAR END PANEL ANTENNA SENSOR	Cracked	485.00 FL	*150.00 FL
9	1	*REAR END PANEL INNER TOP GARNISH	Deformed	287.90 FL	*287.90 FL
10	1	*REAR RH TAILLAMP	Cracked	630.00 FL	*630.00 FL
11	1	*REAR RH TAILLAMP BACK RUBBER GASKET	Necessary	69.50 FL	*20.00 FL
12	1	*REAR RH TAILLAMP LOWER BRACKET	Not Necessary	68.00 FL	*- FL
13	1	*REAR TAILGATE HYBRID EMBLEM	Necessary	50.00 FL	*50.00 FL
14	1	*REAR TAILGATE PRIUS EMBLEM	Necessary	52.30 FL	*52.30 FL
15	1	*REAR TAILGATE WEATHER STRIP	Not Necessary	360.70 FL	*- FL
16	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1	*SET REAR BUMPER LOWER COVER CLIPS	Necessary	20.00 FS	*20.00 FS
18	1	*SET REAR BUMPER LOWER SPOILER CLIPS	Necessary	60.00 FS	*30.00 FS
19	1	*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
20	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
21	1	*SET REAR RH TAILLAMP CLIPS	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,582.65	3,878.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,288.16	889.50
Total Parts (\$\$)	4,294.49	2,988.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	40.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	780.00	600.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	400.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	30.00
Gross Labour Cost (\$\$)			1,770.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >