

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007300/EPA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SJY5519M	Insured Vehicle No :	GBH1065R
Date of Loss:	13/07/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY5519M	Engine No:	G4KEAH861037
Make & Model:	HYUNDAI SANTA FE, 2.4 (A)	Chassis No:	KMHS81BMAU590216
Reg. Date:	14/09/2010 (Man. Year: 2010)	Odometer:	94059 km
Colour:	Grey		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,505.60	2,903.20	602.40	17.18
Miscellaneous Items	351.00	311.00	40.00	11.40
Labour	225.00	225.00	0.00	0.00
Paintwork Labour	617.35	617.35	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,698.95	4,056.55	642.40	13.67
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	4,698.95	3,200.00	1,498.95	31.90
+ GST 7.00/7.00% (\$\$)	328.93	224.00	104.93	31.90
Nett Amount (\$\$)	5,027.88	3,424.00	1,603.88	31.90
+ Loss of Use (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		3,831.49		

INSPECTION

Date of Assignment:	15/07/2020 Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	27/07/2020 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah)
		Blk 1008, #01-04/06/08/94, Bukit

Merah Lane 3
Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2020)
Parts:	M1-SUV	HYUNDAI SANTA FE 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY5519M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE HYUNDAI	Necessary	65.00 FL	*65.00 FL
2	1	NA	*BADGE SANTA FE	Necessary	68.00 FL	*68.00 FL
3	1	NA	*BOOT/TAILGATE LOCK	Bent	120.00 FL	*120.00 FL
4	1	NA	*BOOT/T-GATE MOULDING	Broken	155.00 FL	*155.00 FL
5	1	NA	*BOOTLID/TAILGATE	Dented	1,750.00 FL	*1,750.00 FL
6	1	NA	*REAR BADGE	Necessary	59.00 FL	*59.00 FL
7	1	NA	*REAR BOOM EMBLEM	Necessary	68.00 FL	*68.00 FL
8	1	NA	*REAR BUMPER	Dented	589.00 FL	*589.00 FL
9	1	NA	*REAR BUMPER DAMPING	Broken	108.00 FL	*108.00 FL
10	1	NA	*REAR BUMPER SUPPORT	Bent	270.00 FL	*270.00 FL
11	1	NA	*REAR SCREEN	Not Necessary	657.00 FL	*- FL
12	1	NA	*REAR SCREEN BOND KIT (NPA)	Not Necessary	0.00 FL	*- FL
13	1	NA	*RR BUMPER CLAMP KIT	Necessary	35.00 FL	*35.00 FL
14	1	NA	*RR BUMPER WIND DEFL	Cut	342.00 FL	*342.00 FL
15	1	NA	*TAILGATE HANDLE	Not Necessary	96.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,382.00	3,629.00
- List Item Discount on L Items 20.00/20.00% (S\$)	876.40	725.80
Total Parts (S\$)	3,505.60	2,903.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AUDATEX FEE (NECESSARY)	40.00	40.00
2	1	REAR NO PLATE (NOT NECESSARY)	40.00	0.00
3	1	REAR SCREEN SEALANT (NECESSARY)	60.00	60.00
4	1	REVERES SENSOR (SHORTED)	200.00	200.00
5	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$)			351.00	311.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	445.00	445.00
2	Total Paint Materials	New	172.35	172.35
Labour Items				
3	Total Panel/Mechanical Labour	New	225.00	225.00
Gross Labour Cost (\$)			842.35	842.35

Report was unsubmitted during this print-out.

< END OF ESTIMATES >