

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/ C1120007303/USF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *STT16934*at Workshop m/s: *room*

of _____

Insured: *SKX32B*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *24k.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *7* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

694W

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *STT16934* Yr Regn: *9109*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Toyota* *Vios* c.c. *1497*Colour: *Grey* A/C: Insured / Std / NI / NASp. Reading: *156946* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MR053H49305131748*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *195/60 R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *maximum*

Front

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *11/7/20* D.O.I. *15/7/20*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *net 11616**code 27-9-2024 LTA #12384**have GIA**21/8/20 1/5 = 5000 confirmed with Elin*

(\$ 8,092.12/RED - 62%)

Date/Time, File Pass to?

21/08/2020

1) TYPIST

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: *7*Resurvey No. of Trip: *2*

Survey Fee: _____

Transportation: _____

____ S + RS, ____ SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum I.B.I. (\$ 5,000.00 L/S)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Submit to insurance

Not Authorized 15/7/20
2/5 \$5000 | 7 days.

Take photo After repair

Car Number: SJT1693U

Model: TOYOTA VIOS

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material:

	1	Rear Bumper	427.90
	2	Rear Bumper Side Retainer @ 65.00	
	3	Rear Bumper Bracket @ 78.00	
2/15	4	Rear Bumper reflectors @ 168.00	151 x 2 = 302.00
	5	Rear Bumper Clips	
	6	Rear Bootlid Panel	566.10
	7	Rear Bootlid weatherstrip	
	8	Rear Bootlid Inner Lock	185.40
	9	Rear Bootlid Catch	
	10	Rear Bootlid Logo Emblem	
2/15	11	Rear Taillamps @ 725.80	322.50 x 2 = 645.00
2/15	12	Rear Taillamp Panel @ 385.70	
	13	Rear End Panel	601.10
	14	Rear End Panel Top Garnish	
	15	Rear End Panel Top Garnish Clips	
	16	Rear Fenders @ 1,012.30	
2/15	17	Rear Fender Inner Trim Garnish @ 385.70	
	18	Rear Fender Inner Trim Garnish Clips	
	19	Rear Fender Inner Shield @ 176.00	
	20	Rear Left Fender Inner Shield Clips	
	21	Rear Spare Tyre Top board	
2/15	22	Rear Spare Tyre Top Foam @ 325.60	281.50 x 2 = 563.00
	23	Rear Spare Tyre Panel	680.10

DIS	\$	758.40	✓
Seat	\$	130.00	✓
11	\$	156.00	X
Che	\$	336.00	✓
nu	\$	60.00	✓
Suc/	\$	799.40	✓
Trim	\$	198.70	✓
Trim	\$	195.80	✓
11	\$	58.70	X
nu	\$	75.90	✓
Che	\$	1,451.60	✓
1	\$	771.40	X
Soc/	\$	687.20	✓
Trim	\$	165.80	✓
11	\$	60.00	X
1	\$	2,024.60	X
11	\$	771.40	X
11	\$	80.00	X
11	\$	352.00	X
11	\$	80.00	X
Trim	\$	265.40	✓
Trim	\$	651.20	✓
Crumpled/Suc	\$	980.00	✓

Parts:	\$	11,109.50
Less Parts 25%:	\$	2,777.37
Total Parts:	\$	8,332.12

4866.40

Special Net Items:

- Rear Bootlid Panel Top Spoiler Sealant
- Rear Taillamp Panel Sealant
- Rear End Panel Sealant
- Rear Spare Tyre Panel Sealant
- Rear Number Plate W/Base Garnish
- Reverse Sensor

11	\$	80.00	X
11	\$	60.00	X
nu	\$	80.00	50
11	\$	80.00	X
11	\$	80.00	X
shutle	\$	280.00	200

Total S/N Parts: \$ 660.00

1 set

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,800.00	1200
To Putty, Spray Paint on Affected Accident Areas	\$	1,600.00	1000
To Check & Re-Connect all electrical wiring	\$	50.00	30
To Remove & Install Rear Bootlid Components Trim & Garnish	\$	150.00	60
To Remove & Install Rear Fenders Trim, Garnish	\$	150.00	80
To Conduct Water Leakage Test	\$	150.00	X
To Rust Proof Affected Areas	\$	200.00	90
Total Labour :		\$	4,100.00

TOTAL PARTS :	\$	8,332.12
TOTAL SPECIAL NET ITEM :	\$	660.00
TOTAL LABOUR :	\$	4,100.00
TOTAL REPAIR COST :	\$	13,092.12

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4866.40
252
P- 3649.80
SW - 250.00
L - 2460.00
6259.80
203
5087.84