



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 8800E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR FRAME LH	MTG DISTORTED	2,100.00	1,980.00
1	SIDE MIRROR COVER LH	CUT / DENTED	350.00	281.40
1	SIDE MIRROR GLASS LH	SERVICEABLE	450.00	-
	LESS 10% DISCOUNT		-290.00	-226.14
			2,610.00	2,035.26
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS.		200.00	80.00
	TO SPRAY PAINT ON AFFECTED AREAS.		200.00	60.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC.)	NOT NECESSARY	150.00	-
			550.00	140.00
	GRAND TOTAL		3,160.00	2,175.26
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/AGI20007307/Ktf3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.