

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 11 Sep 2020

Preliminary Advice

Insured Vehicle No : GBD1670P

TP Vehicle No : GBF8801Y

Make : MAXUS G10

Date of Inspection : 16/07/2020

Inspection At : CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD (EUNOS LINK SERVICE CENTER)
330 UBI ROAD 3
SINGAPORE 408650

Accident Date : 13/07/2020

Assignment Date : 10/09/2020

Est. Duration of Repair : 3

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,115.00
Revised Amount	:S\$	2,045.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,045.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp