Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007311/ETF3E2

Date: 11/09/2020

Odometer:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00044522005

Claimant Vehicle GBF8801Y

Insured Vehicle GBD1670P No:

No: Date of Loss:

13/07/2020

Nature of Claim: TP

Claim No:

SNM20D202431C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF8801Y**

Make & Model: MAXUS G10, 1.9 (A) Reg. Date: 03/04/2017 (Man. Year: 2016)

19D4N1PYGB01K018 Engine No: Chassis No: LSKG4GL12HA410055

55629 km

Colour:

White

Engine Capacity: 1850 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 195/55 R15 Rear Tyre Size: Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm Front Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,689.00	695.00	2,994.00	81.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	1,350.00	3,080.00	69.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,119.00	2,045.00	6,074.00	74.81
+ GST 7.00/7.00% (S\$)	568.33	143.15	425.18	74.81
Nett Amount (S\$)	8,687.33	2,188.15	6,499.18	74.81

INSPECTION

Date of Assignment: 10/09/2020

Date Inspected: 16/07/2020 Inspected At: Cycle & Carriage-Fulco Motor Dealer Pte

Ltd (Eunos Link Service Center)

330 UBI ROAD 3 Singapore 408650

Estimated Period of Repair: 3.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 11/9/2020

Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Sep 2020)

Parts: 143 MAXUS G10 1.9 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF8801Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	50.00 FS	*50.00 FS
2	1		*FASCIA-FRT BPR (W/LR	Deformed	437.00 FS	*437.00 FS
3	1		*GRILLE - FRT BPR LWR	Broken	144.00 FS	*144.00 FS
4	1		*LH FRT FOGLIGHT COVE	Cut	10.00 FS	*10.00 FS
5	1		*ABSORBER-FRT BPR ENG	Not Necessary	42.00 FS	*-FS
6	1		*GRILLE ASM-RAD	Not Necessary	171.00 FS	*-FS
7	2		*CLIP-RAD GRL	Necessary	2.00 FS	*2.00 FS
8	1		*LOGO-FRT	Not Necessary	23.00 FS	*-FS
9	1		*CROSSMEMBER ASM-FRT	Not Necessary	1,037.00 FS	*-FS
10	1		*LH SIDE BRACKET	Necessary	6.00 FS	*6.00 FS
11	1		*RH SIDE BRACKET	Necessary	6.00 FS	*6.00 FS
12	10		*CLIP, BUMPER	Necessary	40.00 FS	*40.00 FS
13	1		*LH FRT FOG LAMP	Not Necessary	69.00 FS	*-FS
14	1		*LH HEADLAMP ASSY	Not Necessary	1,652.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett.	_		·
				Total Parts (S\$)	3,689.00	695.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE FRONT BUMPER, REINFORCEMENT, ETC - REPAIR SUPPORT PANEL. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	2,400.00	600.00
4	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	1,680.00	420.00
	Gross Labour Cost (S\$)		4,430.00	1,350.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >