



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



MAXUS

Steve (LKK) 83228813 ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Y.S. Lim Construction Pte Ltd Reg No/Reg Date GBF8801Y / 03/04/2017 Date In/Mileage 14/07/2020/ 0 Chassis No LSKG4GL12HA410055 Engine No 19D4N1PYGB01K018 Make/Model MAXCV/G10D19TMT Colour/Trim WHT White / BK Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	14/07/2020/ 15:56	DS	218 / Marsler	48530			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S MIPNT88088								50.00
FRONT NUMBER PLATE WITH CASING								250.00
S MIPNT88088								80 100.00
DIAGNOSTIC / SCANNING								
S MIPNT88088								690 2400.00
TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS								
S MIPNT88088								420 1680.00
TO REPLACE FRONT BUMPER, REINFORCEMENT, ETC								
-REPAIR SUPPORT PANEL								
STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS								
S MIPNT98088								
SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS								
P NC00071562					1.00	437.00	0.00	437.00
FASCTA-FRT BPR (W/LR)					1.00	144.00	0.00	144.00
P NC00071570					1.00	10.00	0.00	10.00
GRILLE-FRT BPR LWR					1.00	42.00	0.00	42.00
P NC00037357					1.00	171.00	0.00	171.00
LH FRT FOGLIGHT COVE					1.00	1.00	0.00	2.00
P NC00018122					1.00	23.00	0.00	23.00
ABSORBER-FRT BPR ENG					1.00	1037.00	0.00	1037.00
M NC00063826					2.00	6.00	0.00	6.00
GRILLE ASM-RAD					1.00	6.00	0.00	6.00
P NC00008711					1.00	4.00	10.00	40.00
CLIP-RAD GR					1.00	69.00	0.00	69.00
M NC00018364					1.00	1652.00	0.00	1652.00
LOGO-FRT								
P NC00020644-4100								
CROSSMEMBER ASM-FRT								
P NC00024453								
LH SIDE BRACKET								
M NC00024454								
RH SIDE BRACKET								
P JJMR200300								
CLIP, BUMPER								
M NC00036427								
LH FRT FOG LAMP								
P NC00056663								
LH HEADLAMP ASSY								
Z NOTES								
ACCIDENT ON 13/07/2020 ALONG EAST COAST RD								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT VEHICLE								
TP # GBD1670P TP INS : CHINA TAIPING								

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a voluntary basis and is not a requirement of the insurance policy.

No illegal modification(s) is allowed

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Parts	3,635.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,480.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	8,115.00