

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20007313/DBS3Q2

Date: 16/02/2021

### REFERENCE

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D19MFL0005549   |
| <b>Claimant Vehicle No :</b> | SHA8317J                              | <b>Insured Vehicle No :</b> | GBJ766Y         |
| Date of Loss:                | 05/07/2020                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MFL2020D0001248 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHA8317J</b>                   |             |                   |
| Make & Model:               | TOYOTA PRIUS, 1.8 HYBRID CVT (A)  | Engine No:  | 2ZRR969198        |
| Reg. Date:                  | 09/12/2016 (Man. Year: 2016)      | Chassis No: | JTDKB3FUX03538699 |
| Colour:                     | Yellow                            | Odometer:   | 378033 km         |
| Engine Capacity:            | 1798 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65 R15   | Rear Tyre Size:  | 195/65 R15   |
| Front Left Side:  | Davanti 5 mm | Rear Left Side:  | Davanti 5 mm |
| Front Right Side: | Davanti 5 mm | Rear Right Side: | Davanti 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference       | Diff %       |
|--------------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                            | 44,109.69        | 24,915.76        | 19,193.93        | 43.51        |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00             |              |
| Labour                                           | 6,760.00         | 2,830.00         | 3,930.00         | 58.14        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00             |              |
| Towing                                           | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>              | <b>50,869.69</b> | <b>27,745.76</b> | <b>23,123.93</b> | <b>45.46</b> |
| <b>Approved Total (Overridden) (S\$)</b>         |                  | <b>22,000.00</b> |                  |              |
| (S\$)                                            | 50,869.69        | 22,000.00        | 28,869.69        | 56.75        |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | <b>3,560.88</b>  | <b>1,540.00</b>  | <b>2,020.88</b>  | <b>56.75</b> |
| <b>Nett Amount (S\$)</b>                         | <b>54,430.57</b> | <b>23,540.00</b> | <b>30,890.57</b> | <b>56.75</b> |
| <b>+ Loss of Use (16.0 x S\$40.00/day) (S\$)</b> |                  | 640.00           |                  |              |
| <b>+ Car Rental (16.0 x S\$125.40/day) (S\$)</b> |                  | 2,006.40         |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | 7.49             |                  |              |
| <b>+ Other Costs (S\$)</b>                       |                  | 80.00            |                  |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>26,273.89</b> |                  |              |

### INSPECTION

|                             |            |                                                                                                                         |
|-----------------------------|------------|-------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 09/07/2020 |                                                                                                                         |
| Date Inspected:             | 09/07/2020 | Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)<br>8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 10.0 days  |                                                                                                                         |

---

**Adjuster:** BRYAN TANI**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                   |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 08 Jan 2021)                     |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                 |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SHA8317J)                                                                                                                                    |                                                                   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                                    | Torn          | 458.60 FL   | *458.60 FL   |
| 2   | 1   |          | *REAR BUMPER SIDE RETAINER                      | Serviceable   | 112.70 FL   | *- FL        |
| 3   | 1   |          | *REAR BUMPER CLIPS                              | Necessary     | 22.00 FL    | *22.00 FL    |
| 4   | 1   |          | *TAIL LAMP ASSY (UPPER)                         | Not Necessary | 557.90 FL   | *- FL        |
| 5   | 1   |          | *TAIL LAMP ASSY (LOWER)                         | Not Necessary | 548.40 FL   | *- FL        |
| 6   | 1   |          | *REAR FIBER TOOL BOX TRIM (LH)                  | Not Necessary | 598.00 FL   | *- FL        |
| 7   | 1   |          | *REAR FENDER ,LH                                | Buckled       | 836.70 FL   | *836.70 FL   |
| 8   | 1   |          | *REAR FENDER INNER PANEL (LH)                   | Repair        | 728.00 FL   | *- FL        |
| 9   | 1   |          | *REAR FENDER OUTER PANEL ,LH                    | Dented        | 486.00 FL   | *486.00 FL   |
| 10  | 1   |          | *REAR FENDER REINFORCEMENT ,ROCKER PANEL ,LH    | Not Necessary | 552.30 FL   | *- FL        |
| 11  | 1   |          | *REAR FENDER PANEL ,ROOF SIDE OUTER ,LH         | Not Necessary | 311.00 FL   | *- FL        |
| 12  | 1   |          | *REAR FENDER EXTENSION ,ROOF SIDE INNER FRT ,LH | Not Necessary | 265.10 FL   | *- FL        |
| 13  | 1   |          | *REAR FLOOR PANEL SIDE (LH)                     | Not Necessary | 276.20 FL   | *- FL        |
| 14  | 1   |          | *REAR FENDER SHIELD (LH)                        | Deformed      | 174.20 FL   | *174.20 FL   |
| 15  | 1   |          | *REAR FENDER TRIMBOARD (LH)                     | Not Necessary | 725.00 FL   | *- FL        |
| 16  | 1   |          | *REAR FENDER AIR DUCT                           | Not Necessary | 165.10 FL   | *- FL        |
| 17  | 1   |          | *REAR FENDER TOP PANEL INNER                    | Not Necessary | 340.20 FL   | *- FL        |
| 18  | 1   |          | *REAR CHASSIS MEMBER                            | Not Necessary | 1,180.80 FL | *- FL        |
| 19  | 1   |          | *REAR FLOOR PANEL SIDE (LH)                     | Not Necessary | 717.60 FL   | *- FL        |
| 20  | 1   |          | *REAR FLOOR BOARD (LH)                          | Not Necessary | 823.40 FL   | *- FL        |
| 21  | 1   |          | *REAR DOOR RUBBER SEAL OUTER                    | Not Necessary | 257.90 FL   | *- FL        |
| 22  | 1   |          | *PANEL SUB -ASSY ,REAR DOOR ,LH                 | Dented        | 1,258.30 FL | *1,258.30 FL |
| 23  | 1   |          | *REAR DOOR HINGE UPPER                          | Not Necessary | 82.30 FL    | *- FL        |
| 24  | 1   |          | *REAR DOOR HINGE LOWER                          | Not Necessary | 82.30 FL    | *- FL        |
| 25  | 1   |          | *REAR DOOR CHECK                                | Not Necessary | 153.00 FL   | *- FL        |
| 26  | 1   |          | *REAR DOOR TRIMBOARD                            | Not Necessary | 725.00 FL   | *- FL        |
| 27  | 1   |          | *REAR DOOR INNER LOCK                           | Not Necessary | 644.70 FL   | *- FL        |
| 28  | 1   |          | *MOTOR POWER WINDOW REGULATOR FRT ,LH           | Not Necessary | 941.80 FL   | *- FL        |
| 29  | 1   |          | *REGULATOR ,FRONT DOOR WINDOW REAR ,LH          | Not Necessary | 228.40 FL   | *- FL        |
| 30  | 1   |          | *REAR DOOR OUTER HANDLE                         | Cut           | 93.00 FL    | *93.00 FL    |
| 31  | 1   |          | *ROCKER PANEL OUTER GARNISH                     | Broken        | 576.00 FL   | *576.00 FL   |
| 32  | 1   |          | *ROCKER PANEL OUTER                             | Not Necessary | 519.80 FL   | *- FL        |
| 33  | 1   |          | *ROCKER PANEL ENFORCEMENT (LH)                  | Not Necessary | 974.30 FL   | *- FL        |
| 34  | 1   |          | *ROCKER PANEL INNER (LH)                        | Not Necessary | 752.60 FL   | *- FL        |
| 35  | 1   |          | *ROCKER PANEL STEP GARNISH (REAR) (LH)          | Not Necessary | 178.30 FL   | *- FL        |
| 36  | 1   |          | *REAR TYRE (LH) (50%)                           | Torn          | 172.80 FS   | *108.00 FS   |
| 37  | 1   |          | *REAR TYRE RIM (LH)                             | Bent          | 1,555.00 FL | *1,555.00 FL |
| 38  | 1   |          | *REAR WHEEL HUB CAP (LH)                        | Cut           | 177.70 FL   | *177.70 FL   |
| 39  | 1   |          | *REAR WHEEL BEARING & HUB ASSY                  | Damaged       | 610.20 FL   | *610.20 FL   |
| 40  | 1   |          | *REAR CROSS MEMBER                              | Bent          | 2,200.40 FL | *2,200.40 FL |
| 41  | 1   |          | *REAR SHOCK ABSORBER                            | Distorted     | 118.30 FL   | *118.30 FL   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                     | Condition              | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------------|------------------------|-------------|--------------|
| 42  | 1   |          | *REAR SHOCK ABSORBER MOUNTING                   | Not Necessary          | 125.30 FL   | *- FL        |
| 43  | 1   |          | *REAR LOWER ARM                                 | Bent                   | 497.50 FL   | *497.50 FL   |
| 44  | 1   |          | *REAR UPPER ARM                                 | Distorted              | 356.80 FL   | *356.80 FL   |
| 45  | 1   |          | *REAR KNUCKLE ARM                               | Distorted              | 810.60 FL   | *810.60 FL   |
| 46  | 1   |          | *REAR COIL SPRING                               | Not Necessary          | 191.40 FL   | *- FL        |
| 47  | 1   |          | *REAR COIL SPRING MOUNTING                      | Not Necessary          | 125.70 FL   | *- FL        |
| 48  | 1   |          | *REAR BRAKE ABS SENSOR (WIRE)                   | Not Necessary          | 278.80 FL   | *- FL        |
| 49  | 1   |          | *REAR STABILIZER BAR                            | Distorted              | 311.50 FL   | *311.50 FL   |
| 50  | 1   |          | *REAR STABILIZER LINK                           | Distorted              | 151.60 FL   | *151.60 FL   |
| 51  | 1   |          | *REAR TRAILING ARM                              | Distorted              | 314.20 FL   | *314.20 FL   |
| 52  | 1   |          | *REAR ASSIST ARM                                | Distorted              | 342.20 FL   | *342.20 FL   |
| 53  | 1   |          | *REAR HEIGHT SENSOR LH ONLY                     | Bent / Damaged         | 789.30 FL   | *789.30 FL   |
| 54  | 1   |          | *REAR BRAKE HOSE                                | Not Necessary          | 90.70 FL    | *- FL        |
| 55  | 1   |          | *REAR BRAKE CALIPER                             | Not Necessary          | 842.90 FL   | *- FL        |
| 56  | 1   |          | *REAR BRAKE DISC ROTOR                          | Not Necessary          | 416.50 FL   | *- FL        |
| 57  | 1   |          | *RADIATOR GRILLE                                | Deformed               | 438.00 FL   | *438.00 FL   |
| 58  | 1   |          | *RADIATOR GRILLE EMBLEM                         | Necessary              | 88.00 FL    | *88.00 FL    |
| 59  | 1   |          | *FRONT BUMPER COVER                             | Torn                   | 499.90 FL   | *499.90 FL   |
| 60  | 1   |          | *FRONT BUMPER REINFORCEMENT                     | Bent                   | 696.40 FL   | *696.40 FL   |
| 61  | 1   |          | *FRONT BUMPER REINFORCEMENT ABSORBER (O/S)      | Bent                   | 115.70 FL   | *115.70 FL   |
| 62  | 1   |          | *FRONT BUMPER LOWER REINFORCEMENT               | Bent                   | 364.20 FL   | *364.20 FL   |
| 63  | 1   |          | *FRONT BUMPER LOWER REINFORCEMENT BRACKET (O/S) | Buckled                | 330.00 FL   | *165.00 FL   |
| 64  | 1   |          | *FRONT BUMPER SPONGE                            | Torn                   | 78.80 FL    | *78.80 FL    |
| 65  | 1   |          | *FRONT BUMPER LOWER GRILLE                      | Deformed               | 148.60 FL   | *148.60 FL   |
| 66  | 1   |          | *LAMP ASSY ,FOG, RH                             | Cut / Mtg Broken       | 920.00 FL   | *920.00 FL   |
| 67  | 1   |          | *FRONT BUMPER CLIPS                             | Necessary              | 22.00 FL    | *22.00 FL    |
| 68  | 1   |          | *FRONT BUMPER SIDE RETAINER (O/S)               | Mtg Cracked            | 77.00 FL    | *77.00 FL    |
| 69  | 1   |          | *FRONT BUMPER TOP GARNISH                       | Not Necessary          | 225.40 FL   | *- FL        |
| 70  | 1   |          | *COVER ,FRONT BUMPER HOLE ,RH                   | Serviceable            | 28.38 FL    | *- FL        |
| 71  | 1   |          | *ABSORBER ,FRONT BUMPER ,LOWER                  | Deformed / Torn        | 127.70 FL   | *127.70 FL   |
| 72  | 1   |          | *UNIT ASSY ,HEADLAMP ,RH (LED)                  | Mtg Broken             | 3,455.00 FL | *3,455.00 FL |
| 73  | 1   |          | *HEADLAMP ECU                                   | Not Necessary          | 682.60 FL   | *- FL        |
| 74  | 1   |          | *HEAD LAMP PANEL (RH)                           | Dented                 | 240.10 FL   | *240.10 FL   |
| 75  | 1   |          | *TOP PANEL CENTRE                               | Not Necessary          | 364.98 FL   | *- FL        |
| 76  | 1   |          | *TOP PANEL SIDE (O/S )                          | Dented                 | 145.90 FL   | *145.90 FL   |
| 77  | 1   |          | *RADIATOR ASSY                                  | Bent                   | 1,841.80 FL | *1,841.80 FL |
| 78  | 1   |          | *COOLANT                                        | Not Necessary          | 45.00 FL    | *- FL        |
| 79  | 1   |          | *DELECTOR ,RADIATOR SIDE ,RH                    | Deformed               | 83.50 FL    | *83.50 FL    |
| 80  | 1   |          | *RADIATOR FAN BLADE (RH)                        | Not Necessary          | 233.10 FL   | *- FL        |
| 81  | 1   |          | *RADIATOR FAN MOTOR (RH)                        | Not Necessary          | 543.70 FL   | *- FL        |
| 82  | 1   |          | *RADIATOR FAN COWLING (RH)                      | Not Necessary          | 451.30 FL   | *- FL        |
| 83  | 1   |          | *CONDENDER ASSY ,W/RECEIVER                     | Bent                   | 1,336.60 FL | *1,336.60 FL |
| 84  | 1   |          | *FENDER SUB-ASSY ,FRONT RH                      | Repair                 | 945.30 FL   | *- FL        |
| 85  | 1   |          | *FRONT FENDER SHIELD                            | Not Necessary          | 198.50 FL   | *- FL        |
| 86  | 1   |          | *FRONT FENDER SHIELD CLIP                       | Not Necessary          | 14.90 FL    | *- FL        |
| 87  | 1   |          | *FRONT FENDER HYBRID EMBLEM ,RH                 | Serviceable            | 86.50 FL    | *- FL        |
| 88  | 1   |          | *BRACKET ,FRONT SIDE PANEL ,RH                  | Not Necessary          | 86.30 FL    | *- FL        |
| 89  | 1   |          | *REAR BUMPER RUBBER MAT                         | Not Necessary          | 50.00 FS    | *- FS        |
| 90  | 2   |          | *REAR BUMPER ADVERTISEMENT                      | Necessary (1 PCS ONLY) | 240.00 FS   | *120.00 FS   |
| 91  | 1   |          | *REAR FENDER ADVERTISEMENT LOGO (LH)            | Necessary              | 100.00 FS   | *100.00 FS   |
| 92  | 1   |          | *REAR DOOR COMFORT & APPS STICKER               | Necessary              | 80.00 FS    | *80.00 FS    |
| 93  | 1   |          | *REAR DOOR ADVERTISEMENT LOGO                   | Necessary              | 100.00 FS   | *100.00 FS   |
| 94  | 1   |          | *FRONT NO .PLATE                                | Not Necessary          | 25.00 FS    | *- FS        |

 Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------------|---------------|-------------|--------------|
| 95  | 1   |          | *FRONT NO .PLATE TRIM COVER                    | Not Necessary | 30.00 FS    | *- FS        |
| 96  | 1   |          | *FRONT NO .PLATE GARNISH                       | Not Necessary | 99.00 FS    | *- FS        |
| 97  | 1   |          | *FRONT FENDER ADVERTISEMENT LOGO (RH)          | Necessary     | 100.00 FS   | *100.00 FS   |
| 98  | 1   |          | *UNIT ASSY ,HEADLAMP ,LH (LED)                 | Mtg Broken    | 3,455.00 FL | *3,455.00 FL |
| 99  | 1   |          | *CONDENSER ASSY ,/RECEIVER                     | Repeated      | 1,336.60 FL | *- FL        |
| 100 | 1   |          | *AIRCON LIQUID HOSE & PIPE                     | Bent          | 580.45 FL   | *580.45 FL   |
| 101 | 1   |          | *FRONT SUSPENSION LOWER ARM (RH)               | Distorted     | 631.90 FL   | *631.90 FL   |
| 102 | 1   |          | *FRONT SIDE MEMBER REINFORCEMENT PANEL (RH)    | Dented        | 320.40 FL   | *320.40 FL   |
| 103 | 1   |          | *FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH) | Repeated      | 330.00 FL   | *- FL        |
| 104 | 1   |          | *FRONT SIDE MEMBER SIDE COVER (RH)             | Torn          | 172.55 FL   | *172.55 FL   |
| 105 | 1   |          | *FRONT LOWER PANEL                             | Bent          | 320.60 FL   | *320.60 FL   |
| 106 | 1   |          | *GUIDE RADIATOR AIR NO.3                       | Repeated      | 229.80 FL   | *- FL        |
| 107 | 1   |          | *FRONT LOWER SIDE RAIL (RH)                    | Bent          | 230.75 FL   | *230.75 FL   |
| 108 | 1   |          | *ENGINE UNDER COVER CENTER                     | Torn          | 523.50 FL   | *523.50 FL   |
| 109 | 1   |          | *ENGINE UNDER COVER FRONT                      | Torn          | 288.30 FL   | *288.30 FL   |
| 110 | 1   |          | *ENGINE CROSS MEMBER                           | Bent          | 2,504.40 FL | *2,504.40 FL |
| 111 | 1   |          | *FRONT SHOCK ABSORBER (RH)                     | Distorted     | 398.20 FL   | *398.20 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>54,887.91</b> | <b>33,018.35</b> |
| <b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b> | 10,778.22        | 8,102.59         |
| <b>Total Parts (\$\$)</b>                                  | <b>44,109.69</b> | <b>24,915.76</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                            |          |                 |                 |
| 1                              | PANEL BEATING                              | New      | 2,000.00        | 1,200.00        |
| 2                              | SPRAY PAINTING CHARGE                      | New      | 1,800.00        | 900.00          |
| 3                              | WIRING CHARGE                              | New      | 120.00          | 30.00           |
| 4                              | TUFF KOTE                                  | New      | 160.00          | 40.00           |
| 5                              | TOWING CHARGE                              | New      | 80.00           | 0.00            |
| 6                              | REMOVE/REFIX CUSHION & UPHOLSTERY REAR     | New      | 150.00          | 80.00           |
| 7                              | REMOVE/REFIX REVERSE SENSOR                | New      | 120.00          | 0.00            |
| 8                              | REMOVE/REFIX UNDERCARRIAGE (RR)            | New      | 400.00          | 150.00          |
| 9                              | RE-SET REAR ABS SYSTEM                     | New      | 400.00          | 0.00            |
| 10                             | REMOVE/REFIX FUEL TANK                     | New      | 80.00           | 0.00            |
| 11                             | REMOVE/REFIX EXHAUST PIPE                  | New      | 80.00           | 0.00            |
| 12                             | TRANSFER OF DOOR MECHANISM REAR            | New      | 80.00           | 60.00           |
| 13                             | RE-SET REAR POWER WINDOW SYSTEM            | New      | 200.00          | 0.00            |
| 14                             | FOUR WHEEL ALIGNMENT                       | New      | 120.00          | 60.00           |
| 15                             | REMOVE/REFIX RADIATOR                      | New      | 90.00           | 80.00           |
| 16                             | REMOVE/REFIX AIRCON & REFILL GAS           | New      | 130.00          | 80.00           |
| 17                             | REMOVE/REFIX FUSE BOX                      | New      | 120.00          | 0.00            |
| 18                             | REPAIR EXHAUST PIPE                        | New      | 80.00           | 0.00            |
| 19                             | DIAGNOSTIC & RESETTING TO ERASE FAULT CODE | New      | 550.00          | 150.00          |
| <b>Gross Labour Cost (S\$)</b> |                                            |          | <b>6,760.00</b> | <b>2,830.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >