



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 2665J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN GLASS (SENSOR TYPE) (N) (WCP)	SCRATCHED	1,150.00	1,150.00
1	FRONT WINDSCREEN GLASS MOULDING (N) (WCP)	CRUMPLED	35.00	35.00
1	FRONT WINDSCREEN GLASS RH DEFLECTOR (N) (WCP)	SCRATCHED	95.00	95.00
1	FRONT WIPER ARM RH (N) (WCP)	SCRATCHED	85.00	85.00
1	FRONT WIPER ARM LH (N) (WCP)	SERVICEABLE	85.00	-
1	FRONT WIPER BLADE - LONG (N) (WCP)	SCRATCHED	60.00	60.00
1	FRONT WIPER BLADE - SHORT (N) (WCP)	SERVICEABLE	30.00	-
1	FRONT RH DOOR GLASS (N) (WCP)	SERVICEABLE	550.00	-
1	RH WING MIRROR MOTOR (N) (WCP)	CRUMPLED	325.00	325.00
1	RH WING MIRROR COVER (N) (WCP)	CRUMPLED	65.00	65.00
1	EMBLEM - HYBRID (N) (WCP)	NECESSARY	40.00	40.00
1	RH HEADLAMP (N) (WCP)	SERVICEABLE	1,050.00	-
1	RH FRONT QUATER GLASS (N) (WCP)	SERVICEABLE	200.00	-
1	FRONT WIPER GARNISH (N) (WCP)	SCRATCHED	285.00	285.00
1	FRONT RH DOOR FRAME STICKER - FRONT (N) (WCP)	SERVICEABLE	20.00	-
1	FRONT RH DOOR FRAME STICKER - TOP (N) (WCP)	SERVICEABLE	25.00	-
1	FRONT RH DOOR FRAME STICKER - REAR (N) (WCP)	SERVICEABLE	30.00	-
	COST PLUS 15%		619.50	321.00
			4,749.50	2,461.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	RH FRONT QUATER GLASS SEALANT (SN)	SERVICEABLE	20.00	-
			60.00	40.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT FRONT DOOR GLASS.		150.00	120.00
	TO REMOVE AND REFIT FRONT RH QUATER GLASS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT FRONT RH DOOR GLASS.	NOT NECESSARY	80.00	-
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS.		600.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,100.00	900.00
			2,050.00	1,220.00
GRAND TOTAL			6,859.50	3,721.00
RECOMMENDED COST OF REPAIRS				3,721.00

Report Ref No. CS1/SGK20007315/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.