



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008604

INV Date 30/12/2020

Reference CC4/FCI20007318/Kes3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SME 5820L

Insured Veh. SHA 7870J

Claim No. D20002770MFSH

Policy No. D-20094922MFSH

Accident Date 11/07/2020

Inspection Date 27/07/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI20007318/Kes3q2 Date: 30/12/2020 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7870J	Veh. Inspected	SME 5820L
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20002770MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	15/07/2020
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71217438	Colour	METALLIC GREY
Odometer	36859 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/07/2020	Inspection Date	27/07/2020
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 5820L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	986.90	986.90
1	REAR TAILGATE 'SHUTTLE' EMBLEM	NECESSARY	46.60	46.60
1	REAR TAILGATE 'HYBRID' EMBLEM	NECESSARY	56.20	56.20
1	REAR TAILGATE LOGO EMBLEM	NECESSARY	48.50	48.50
1	REAR WINDSCREEN RUBBER	NECESSARY	68.70	68.70
8	REAR TAILGATE INNER TRIM CLIPS @\$5.50	NOT NECESSARY	44.00	-
1	REAR BUMPER	BUCKLED / DENTED	783.70	783.70
8	REAR BUMPER CLIPS @\$5.80	NECESSARY	46.40	46.40
1	REAR BUMPER FIXING COVER	DENTED	38.40	38.40
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-423.88	-415.08
			1,695.52	1,660.32
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
2	REAR WINDSCREEN STOPPER @\$15.00(SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	MISSING	350.00	200.00
			440.00	270.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	500.00
	LABOUR CHARGE FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC.		700.00	600.00
	LABOUR CHARGES TO REPLACE ,REMOVE ,REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT ,REAR WINDSCREEN MOULDING & ETC TO EFFECT REPLACE OF REAR TAILGATE.		150.00	120.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATIONS.		120.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC .TO EFFECT REPLACE OF REAR BUMPER .		100.00	50.00
	LABOUR CHARGES TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.		80.00	20.00
			1,750.00	1,350.00
GRAND TOTAL			3,885.52	3,280.32
RECOMMENDED COST OF REPAIRS				3,280.32

Report Ref No. CC4/FC120007318/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5820L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

