



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2006024
INV Date 03/09/2020
Reference CC4/LPC20007320/Ubs3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. FL 7080M
Insured Veh. GR 9275L
Claim No. 19/20/20/VC05/023295
Policy No. Z19VC05004115
Accident Date 04/04/2020
Inspection Date 16/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC20007320/Ubs3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 03-09-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GR 9275L	Veh. Inspected	FL 7080M	
Policy No.	Z19VC05004115	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023295	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	15/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA XR 400 RT	c.c	398	
Engine No.	HIDDEN	Year of Reg.	1996	
Chassis No.	JH2NE03UXTM000789	Colour	RED / BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90-90-21	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	4.10-18	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2020	Inspection Date	16/07/2020	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FL 7080M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	METER ASSY	BROKEN	180.00	180.00
2	FRONT FORK ASSY	O/S BENT	3,600.00	1,650.00
1	FORK UNDER BRACKET	SERVICEABLE	550.00	-
1	HANDLE-BAR	BENT	160.00	160.00
1	BRAKE LEVER	NOT NECESSARY	95.00	-
1	HANDLE-GULP	TORN	180.00	125.00
1	HAND GUARD	CUT	220.00	220.00
1	HEADLAMP	BROKEN	140.00	140.00
2	FRONT SIGNALES-R/L/H	BROKEN	130.00	130.00
1	FRONT FENDER	CRACKED	110.00	110.00
1	FRONT FAIRING	CRACKED	90.00	90.00
1	FRONT BRAKE DISC	NOT NECESSARY	280.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	230.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	65.00	-
1	BRAKE PEDAL	BENT	120.00	120.00
1	FRONT FOOTREST-R/H	TWISTED	80.00	80.00
1	PILLION FOOTREST-R/H	SERVICEABLE	65.00	-
1	EXHAUST COVER	TO REPAIR SEE LABOUR	160.00	-
1	REAR SIDE COVER-R/H	CRACKED	130.00	130.00
1	EXHAUST PIPE ASSY	TO REPAIR SEE LABOUR	550.00	-
1	CLUTCH CABLE	TWISTED	55.00	55.00
1	FUEL TANK	TO REPAIR SEE LABOUR	650.00	-
1	TANK COVER	TORN	250.00	250.00
1	CLUTCH SIDE ENGINE COVER (CUT)	NOT CONSISTENT WITH THE IMPACT	190.00	-
1	CLUTCH COVER GASKET	NOT NECESSARY	30.00	-
	LESS 10% DISCOUNT		-831.00	-344.00
			7,479.00	3,096.00

Report Ref No. CC4/LPC20007320/Ubs3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	SCRATCHED	28.00	10.00
1	FRONT TYRE (SN)	NOT NECESSARY	150.00	-
1	ENGINE OIL (SN)	NOT NECESSARY	22.00	-
1	BEARING CONE (SN)	NECESSARY	120.00	60.00
			320.00	70.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	280.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT RIM,EXHAUST COVER,EXHAUST PIPE ASSY AND FUEL TANK.		450.00	300.00
			780.00	335.00
	GRAND TOTAL		8,579.00	3,501.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CC4/LPC20007320/Ubs3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.