Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007324/UBS3Q2

Date: 03/09/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant FBG9237P Insured Vehicle No: SHB4201E

Vehicle No:

Date of Loss: 30/06/2020 Nature of Claim: TP Claim No: MCT20060362

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**FBG9237P** Reg No:

Make & Model: PIAGGIO VESPA LX, 155cc I.E. 3V Engine No: M688M1001179 Chassis No: Reg. Date: 07/01/2013 (Man. Year: 2012) ZAPM6840000002106 Odometer: 50197 km

Colour: Red

**Engine Capacity:** 155 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 120/70 R11 Rear Tyre Size: 120/70 R10 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,870.00	1,215.10	3,654.90	75.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	780.00	520.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,170.00	1,995.10	4,174.90	67.66
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,170.00	1,500.00	4,670.00	75.69
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Ne	tt Liability (S\$)	1,620.00		

**INSPECTION** 

Date of Assignment: 15/07/2020

Date Inspected: 15/07/2020 Inspected At: Erofia Motor Trading Pte Ltd (KAKI

BUKIT)

1 KAKÍ BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Aug 2020)

Parts: N/A PIAGGIO VESPA LX 155cc I.E. 3V (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBG9237P)

**Particulars** 

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

**Amount** 

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No. Qtv Part No.

		r ai ticulai 5	Condition	itepairer 5	Amount
1		*HANDLE-BAR	Not Necessary	220.00 FL	*- FL
1		*MIRROR -R/H	Not Necessary	80.00 FL	*- FL
1		*HANDLE GRIP-R/H	Not Necessary	40.00 FL	*- FL
1		*COMPLETE BODY KEY & CDI	Repair	1,800.00 FL	*-FL
1		*BRAKE LEVER	Serviceable	65.00 FL	*-FL
1		*FRONT SIGNAL -R/H	Not Necessary	70.00 FL	*- FL
1		*FRONT SIDE LIVING -R/H	Scratched	120.00 FL	*120.00 FL
1		*FOOT MAT	Torn	180.00 FL	*180.00 FL
1		*FOOT STEP	Cut	160.00 FL	*125.00 FL
1		*REAR PROTECTOR BAR	Bent / Cut	450.00 FL	*450.00 FL
1		*HANDLE FRONT COVER	Cut	230.00 FL	*199.00 FL
1		*EXHAUST PIPE ASSY	Repair	900.00 FL	*- FL
1		*EXHAUST COVER	Cut	65.00 FL	*65.00 FL
1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
1		*REAR BOX	Repair	550.00 FS	*-FS
1		*SET STICKER AMBER	Necessary	180.00 FS	*180.00 FS
1		*FRONT FORK REPAIR	Not Necessary	90.00 FS	*-FS
1		*BEARING CONE	Not Necessary	80.00 FS	*-FS
nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
			Sub Total (S\$)	5,308.00	1,329.00
	- List Item Discount on L Items 10.00/10.00% (S\$)		438.00	113.90	
			Total Parts (S\$)	4,870.00	1,215.10
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 *HANDLE-BAR 1 *MIRROR -R/H 1 *HANDLE GRIP-R/H 1 *COMPLETE BODY KEY & CDI 1 *BRAKE LEVER 1 *FRONT SIGNAL -R/H 1 *FRONT SIDE LIVING -R/H 1 *FOOT MAT 1 *FOOT STEP 1 *REAR PROTECTOR BAR 1 *HANDLE FRONT COVER 1 *EXHAUST PIPE ASSY 1 *EXHAUST COVER 1 *SET NUMBER PLATE 1 *REAR BOX 1 *SET STICKER AMBER 1 *FRONT FORK REPAIR 1 *BEARING CONE	*HANDLE-BAR Not Necessary  *MIRROR -R/H Not Necessary  *HANDLE GRIP-R/H Not Necessary  *COMPLETE BODY KEY & CDI Repair  *BRAKE LEVER Serviceable  *FRONT SIGNAL -R/H Not Necessary  *FRONT SIDE LIVING -R/H Scratched  *FOOT MAT Torn  *FOOT STEP Cut  *FOOT STEP Cut  *REAR PROTECTOR BAR Bent / Cut  **REAR PROTECTOR BAR Bent / Cut  **EXHAUST PIPE ASSY Repair  *EXHAUST COVER Cut  **SET NUMBER PLATE Necessary  **SET NUMBER PLATE Necessary  **SET STICKER AMBER Necessary  **SET STICKER AMBER Necessary  **SET STICKER AMBER Not Necessary  **TRONT FORK REPAIR NECESSARY  **TRONT FORK REPA	1         *HANDLE-BAR         Not Necessary         220.00 FL           1         *MIRROR -R/H         Not Necessary         80.00 FL           1         *HANDLE GRIP-R/H         Not Necessary         40.00 FL           1         *COMPLETE BODY KEY & CDI         Repair         1,800.00 FL           1         *BRAKE LEVER         Serviceable         65.00 FL           1         *FRONT SIGNAL -R/H         Not Necessary         70.00 FL           1         *FRONT SIDE LIVING -R/H         Scratched         120.00 FL           1         *FOOT MAT         Torn         180.00 FL           1         *FOOT STEP         Cut         160.00 FL           1         *REAR PROTECTOR BAR         Bent / Cut         450.00 FL           1         *REAR PROTECTOR BAR         Bent / Cut         450.00 FL           1         *BEAHAUST COVER         Cut         230.00 FL           1         *EXHAUST COVER         Cut         65.00 FL           1         *SET NUMBER PLATE         Necessary         28.00 FS           1         *SET STICKER AMBER         Necessary         180.00 FS           1         *FRONT FORK REPAIR         Not Necessary         90.00 FS           1

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO SPRAY PAINT WORK	New	650.00	480.00
3	TO REPAIR BODY FRAME	New	220.00	0.00
4	TO PROVIDE LABOUR	New	380.00	300.00
		Gross Labour Cost (S\$)	1,300.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >