

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007339/EES3Q2

**Date:** 12/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2000004051

**Claimant**  
**Vehicle No :** SCG623E **Insured Vehicle No :** SMR6248P

Date of Loss: 11/07/2020 Nature of Claim: TP Claim No: 6587694928SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SCG623E</b>		
Make & Model:	BMW 116D, 1.5 D 5DR HATCH LED (A)	Engine No:	32159537B37D15A
Reg. Date:	11/04/2016 (Man. Year: 2016)	Chassis No:	WBA1V72000V724394
Colour:	Blue	Odometer:	63555 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,146.00	1,934.40	211.60	9.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	800.00	300.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,246.00</b>	<b>2,734.40</b>	<b>511.60</b>	<b>15.76</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	3,246.00	2,200.00	1,046.00	32.22
<b>+ GST 7.00/7.00% (S\$)</b>	227.22	154.00	73.22	32.22
<b>Nett Amount (S\$)</b>	<b>3,473.22</b>	<b>2,354.00</b>	<b>1,119.22</b>	<b>32.22</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>Nett Liability (S\$)</b>		<b>2,594.00</b>		

### INSPECTION

Date of Assignment: 15/07/2020

Date Inspected: 16/07/2020 Inspected At:

Convergence Automotive Pte Ltd (HQ)  
13 Kaki Bukit Avenue 4, Bartley Biz  
Centre, #01-04  
Singapore 417807

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,150.00 F	*1,150.00 FL
2	1		*REAR BUMPER	Deformed	966.00 F	*966.00 FL
3	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
					<b>Sub Total (\$)</b>	<b>2,146.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	<b>211.60</b>
					<b>Total Parts (\$)</b>	<b>1,934.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	500.00	400.00
2	SPRAY PAINT PANEL	New	600.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,100.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**