

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007341/R1TF3E2

Date: 11/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN17597419022
Claimant Vehicle No :	SLK4507D	Insured Vehicle No :	PC8081H
Date of Loss:	14/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202451/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK4507D	Engine No:	L15B4530771
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1830GX200771
Reg. Date:	17/01/2017 (Man. Year: 2016)	Odometer:	30899 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	700.56	700.56	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	1,000.00	280.00	21.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,980.56	1,700.56	280.00	14.14
+ GST 7.00/7.00% (S\$)	138.64	119.04	19.60	14.14
Nett Amount (S\$)	2,119.20	1,819.60	299.60	14.14

INSPECTION

Date of Assignment:	15/07/2020	
Date Inspected:	20/07/2020	Inspected At:
		Charn's Customcraft (HQ)
		Block 1010 Bukit Merah Lane 3, #01-105
		Singapore 159724
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2020)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4507D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	508.70 FL	*508.70 FL
2	1		*REAR BUMPER CORNER PAD RH	Scratched	195.00 FL	*195.00 FL
3	1		*REAR FENDER WHEEL ARCH RH	Scratched	172.00 FL	*172.00 FL
					Sub Total (\$\$)	875.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	175.14
					Total Parts (\$\$)	700.56

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR AND STRAIGHTEN REAR END PANEL,REAR FENDER RH INCLUSIVE REPLACING THE ABOVE PARTS	New	480.00	400.00
2	PUTTY AND RESPRAY REAR END PANEL,REAR BUMPER,REAR FENDER RH,REAR FENDER ARCH PROTECTOR AND REAR DOOR RH	New	800.00	600.00
Gross Labour Cost (S\$)			1,280.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >