

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2005608

INV Date 14/08/2020

Reference CC3/EQI20007342/Qga3s2

Code EQ

#### **PROFESSIONAL SERVICE FEE**

Vehicle No. SHB 1722M

Insured Veh. SJN 7337R

Claim No. DM20HO01035

Policy No.

Accident Date 08/07/2020

Inspection Date 09/07/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

NSA



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
EQ II	NSURANCE COMPANY LTD Ref : CC3/EQI20007342/Qga3s2			/Qga3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 14-08-2020  Code: EQI			
1.		Policy Particulars	- THIRD PARTY CLAIM		
	Insured Veh.	SJN 7337R	Veh. Inspected	SHB 1722M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	DM20HO01035	Excess (\$)	0.00	
	Assign From		Assign Date	09/07/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA PRIUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JTDKN36UX05757173	Colour	MAROON	
	Odometer	755805	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.		Conditie	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	08/07/2020	Inspection Date	09/07/2020	
	Survey held at	SMRT AUTOMOTIVE SERVICES	S PTE LTD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1722M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	UNDER COVER SUBASSY, RR FLOOR	SERVICEABLE	514.50	-
1	TAILGATE ASY	SERVICEABLE	1,007.90	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	END PANEL	SERVICEABLE	602.10	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	FLOOR PANEL RR / RH	SERVICEABLE	209.90	-
1	BOARD ASSY, RR RH	SERVICEABLE	379.20	-
1	SPACER, RR FLOOR	SERVICEABLE	130.60	-
1	PANEL ASSY, DECK RH	SERVICEABLE	307.00	-
1	BATTERY	SERVICEABLE	278.00	-
1	BATTERY CLAMP	SERVICEABLE	16.10	-
1	BATTERY TRAY	SERVICEABLE	42.80	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-
1	TAIL LAMP RH	SERVICEABLE	557.80	-
1	FENDER RR/RH	SERVICEABLE	766.80	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	FENDER LINER RR/RH	SERVICEABLE	141.30	-
1	DUCT ASSY, QUARTER	SERVICEABLE	70.40	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-

Report Ref No. CC3/EQI20007342/Qga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,150.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			7,489.58	772.91
	LABOUR			
	PANEL BEATING & BODYWORK.		845.00	200.00
	SPRAY PAINT.		1,854.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,359.00	470.00
	GRAND TOTAL		10,848.58	1,242.91

Report Ref No. CC3/EQI20007342/Qga3s2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

Ja

OI SUN PIN

Asst. Automotive Assessor

mon

**HO LEONG CHUAN** 

**Automotive Assessor** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### PHOTOGRAPHS FOR VEHICLE NO. SHB 1722M

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHB 1722M

#### RE-INSPECTION







