

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20007345/ASF3E2

**Date:** 23/09/2020

### REFERENCE

|                       |                                               |                      |                        |
|-----------------------|-----------------------------------------------|----------------------|------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN30420619011      |
| Claimant Vehicle No : | SLU5385D                                      | Insured Vehicle No : | GBF1416Y               |
| Date of Loss:         | 14/07/2020                                    | Nature of Claim:     | TP                     |
|                       |                                               | Claim No:            | SNM20D202449/C02/TAYHP |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                          |             |              |
|-----------------------------|------------------------------------------|-------------|--------------|
| Reg No:                     | SLU5385D                                 | Engine No:  | 2ARH615137   |
| Make & Model:               | TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A) | Chassis No: | AGH300035386 |
| Reg. Date:                  | 20/06/2016 (Man. Year: 2015)             | Odometer:   | 177604 km    |
| Colour:                     | Black                                    |             |              |
| Engine Capacity:            | 2493 cc                                  |             |              |
| Market Value/New Car Price: | N/A                                      |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>        |             |              |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 245/40 R20  | Rear Tyre Size:  | 245/40 R20  |
| Front Left Side:  | Delium 6 mm | Rear Left Side:  | Delium 6 mm |
| Front Right Side: | Delium 6 mm | Rear Right Side: | Delium 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 17,131.35         | 9,207.40          | 7,923.95          | 46.25         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,760.00          | 1,080.00          | 2,680.00          | 71.28         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>20,891.35</b>  | <b>10,287.40</b>  | <b>10,603.95</b>  | <b>50.76</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>8,200.00</b>   |                   |               |
| <b>(S\$)</b>                             | 20,891.35         | 8,200.00          | 12,691.35         | 60.75         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,462.39          | 574.00            | 888.39            | 60.75         |
| <b>Nett Amount (S\$)</b>                 | <b>22,353.74</b>  | <b>8,774.00</b>   | <b>13,579.74</b>  | <b>60.75</b>  |

### INSPECTION

|                             |                          |                                                                                                       |
|-----------------------------|--------------------------|-------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 16/07/2020               |                                                                                                       |
| Date Inspected:             | 20/07/2020 Inspected At: | Dynamic Autowork Pte. Ltd (HQ)<br>8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 4.0 days                 |                                                                                                       |

---

**Adjuster:** ADRIAN LING**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 23 Sep 2020)                             |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLU5385D)                                                                                                                                    |                                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                           |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                               | Deformed      | 1,854.20 FL | *1,614.00 FL |
| 2   | 2   |          | *FRONT BUMPER FOG LAMP                      | Not Necessary | 554.60 FL   | *- FL        |
| 3   | 2   |          | *FRONT BUMPER FOG LAMP COVER C/W CHROME     | Not Necessary | 459.20 FL   | *- FL        |
| 4   | 1   |          | *FRONT BUMPER CENTER COVER GARNISH          | Not Necessary | 25.70 FL    | *- FL        |
| 5   | 1   |          | *FRONT BUMPER LOWER GRILLE                  | Not Necessary | 178.60 FL   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER SENSOR WIRE HARNESS           | Not Necessary | 760.00 FL   | *- FL        |
| 7   | 1   |          | *FRONT BUMPER SIDE RETAINER                 | Necessary     | 95.00 FL    | *95.00 FL    |
| 8   | 1   |          | *FRONT BUMPER SPONGE                        | Not Necessary | 138.10 FL   | *- FL        |
| 9   | 1   |          | *FRONT BUMPER BOTTOM COVER                  | Not Necessary | 240.00 FL   | *- FL        |
| 10  | 1   |          | *FRONT BUMPER REINFORCEMENT                 | Not Necessary | 446.90 FL   | *- FL        |
| 11  | 1   |          | *FRONT GRILLE                               | Cracked       | 1,468.50 FL | *1,205.00 FL |
| 12  | 1   |          | *FRONT CENTER UPPER GRILLE CHROME           | Cracked       | 682.20 FL   | *372.00 FL   |
| 13  | 1   |          | *FRONT GRILLE LOGO                          | Necessary     | 87.70 FL    | *87.70 FL    |
| 14  | 2   |          | *FRONT GRILLE UPPER SIDE MOULDING           | Not Necessary | 296.20 FL   | *- FL        |
| 15  | 1   |          | *FRONT GRILLE LOWER MOULDING CHROME         | Cracked       | 380.00 FL   | *380.00 FL   |
| 16  | 1   |          | *FRONT GRILLE CENTER MOULDING               | Not Necessary | 350.00 FL   | *- FL        |
| 17  | 4   |          | *FRONT GRILLE TOP RUBBER                    | Not Necessary | 267.20 FL   | *- FL        |
| 18  | 2   |          | *HEADLAMP (HID)                             | Cracked       | 7,277.20 FL | *6,462.00 FL |
| 19  | 1   |          | *BONNET                                     | Dented        | 816.50 FL   | *816.50 FL   |
| 20  | 2   |          | *BONNET HINGE                               | Not Necessary | 159.20 FL   | *- FL        |
| 21  | 1   |          | *BONNET CHROME                              | Cut           | 530.40 FL   | *431.00 FL   |
| 22  | 1   |          | *BONNET LOCK                                | Not Necessary | 130.00 FL   | *- FL        |
| 23  | 1   |          | *FRONT BRACE PANEL                          | Not Necessary | 95.00 FL    | *- FL        |
| 24  | 1   |          | *FRONT SUPPORT PANEL                        | Not Necessary | 674.20 FL   | *- FL        |
| 25  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH            | Not Necessary | 290.10 FL   | *- FL        |
| 26  | 2   |          | *HORN                                       | Not Necessary | 260.00 FL   | *- FL        |
| 27  | 2   |          | *AIR CON CONDENSER SIDE GARNISH             | Not Necessary | 155.00 FL   | *- FL        |
| 28  | 1   |          | *FRONT OUTSIDE TEMPERATURE SENSOR           | Not Necessary | 287.30 FL   | *- FL        |
| 29  | 1   |          | *FRONT NUMBER PLATE (SPECIAL TYPE)          | Not Necessary | 180.00 FS   | *- FS        |
| 30  | 1   |          | *SET FRONT BUMPER CLIP                      | Necessary     | 80.00 FS    | *30.00 FS    |
| 31  | 1   |          | *SET FRONT BUMPER CENTER COVER GARNISH CLIP | Not Necessary | 60.00 FS    | *- FS        |
| 32  | 1   |          | *FRONT BUMPER STICKER (SPECIAL TYPE)        | Necessary     | 680.00 FS   | *280.00 FS   |
| 33  | 1   |          | *SET FRONT GRILLE CLIP                      | Necessary     | 30.00 FS    | *20.00 FS    |
| 34  | 1   |          | *BONNET SEALANT                             | Not Necessary | 150.00 FS   | *- FS        |
| 35  | 1   |          | *SET BONNET INSULATOR CLIP                  | Not Necessary | 30.00 FS    | *- FS        |
| 36  | 1   |          | *BONNET STICKER (SPECIAL TYPE)              | Necessary     | 680.00 FS   | *280.00 FS   |
| 37  | 1   |          | *FRONT SUPPORT PANEL SEALANT                | Not Necessary | 150.00 FS   | *- FS        |
| 38  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH            | Not Necessary | 60.00 FS    | *- FS        |
| 39  | 1   |          | *AIR CON CONDENSER SIDE GARNISH             | Not Necessary | 60.00 FS    | *- FS        |

Report was unsubmitted during this print-out.

| No.                                          | Qty | Part No. | Particulars          | Condition     | Repairer's                                                 | Amount           |
|----------------------------------------------|-----|----------|----------------------|---------------|------------------------------------------------------------|------------------|
| 40                                           | 1   |          | *COOLANT             | Not Necessary | 180.00 FS                                                  | *- FS            |
| 41                                           | 2   |          | *FRONT BUMPER SENSOR | Not Necessary | 762.80 FL                                                  | *- FL            |
| F=Franchise part. S=SpcNett. L=ListItemDisc. |     |          |                      |               |                                                            |                  |
|                                              |     |          |                      |               | <b>Sub Total (\$\$)</b>                                    | <b>22,061.80</b> |
|                                              |     |          |                      |               | <b>12,073.20</b>                                           |                  |
|                                              |     |          |                      |               | <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>4,930.45</b>  |
|                                              |     |          |                      |               |                                                            | <b>2,865.80</b>  |
|                                              |     |          |                      |               | <b>Total Parts (\$\$)</b>                                  | <b>17,131.35</b> |
|                                              |     |          |                      |               |                                                            | <b>9,207.40</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                     | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                                                 |          |                 |                 |
| 1                              | SPRAY PAINTING TO AFFECTED AREA                                                                 | New      | 1,400.00        | 500.00          |
| 2                              | TUFF COAT                                                                                       | New      | 250.00          | 0.00            |
| 3                              | WIRING CHECK                                                                                    | New      | 250.00          | 30.00           |
| 4                              | REMOVE AND REFIX FRONT SENSOR                                                                   | New      | 80.00           | 50.00           |
| 5                              | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS                                         | New      | 120.00          | 0.00            |
| 6                              | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST                                             | New      | 80.00           | 0.00            |
| 7                              | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| 8                              | PANEL BEATING, REMOVING AND REPLACING PARTS                                                     | New      | 1,400.00        | 500.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                 |          | <b>3,760.00</b> | <b>1,080.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >