

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007346/KTF3E2

Date: 08/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00055642003	
Claimant Vehicle No :	SLZ4871Y	Insured Vehicle No :	SLD2982P	
Date of Loss:	13/07/2020	Nature of Claim:	TP	Claim No: SNM20D202430/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ4871Y	Engine No:	LEB6546997
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71205651
Reg. Date:	04/05/2018 (Man. Year: 2018)	Odometer:	188692 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,678.80	4,466.00	1,212.80	21.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,330.00	980.00	42.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,988.80	5,796.00	2,192.80	27.45
+ GST 7.00/7.00% (S\$)	559.22	405.72	153.50	27.45
Nett Amount (S\$)	8,548.02	6,201.72	2,346.30	27.45

INSPECTION

Date of Assignment:	16/07/2020	
Date Inspected:	16/07/2020 Inspected At:	385 Sin Ming Drive (S) 575718 (Inside Vicom)
		Repairer : Esteem Performance Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Aug 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ4871Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,080.00 FL	*1,080.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	20.40 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	20.40 FL	*- FL
5	1		*FRONT BUMPER BRACKET LH	Repair	38.00 FL	*- FL
6	1		*FRONT BUMPER BRACKET RH	Repair	38.00 FL	*- FL
7	1		*HEADLAMP RH	Mtg Cracked	2,250.00 FL	*2,250.00 FL
8	1		*RH WING MIRROR (BACK) }	Cracked	587.50 FL	*587.50 FL
9	1		*RH WING MIRROR (GLASS) }		0.00 FL	*- FL
10	1		*RH WING MIRROR (COVER)	Missing	57.30 FL	*57.30 FL
11	1		*RH FRONT DOOR	Bent	787.20 FL	*787.20 FL
12	1		*RH WING MIRROR (COVER)	Repeated	57.30 FL	*- FL
13	1		*RH FRONT DOOR	Repeated	787.20 FL	*- FL
14	1		*RH FRONT DOOR HINGE TOP	Repair	58.60 FL	*- FL
15	1		*RH FRONT DOOR HINGE BOTTOM	Repair	58.60 FL	*- FL
16	1		*RH FRONT DOOR STAND PILLAR STICKER	Necessary	35.80 FL	*35.80 FL
17	1		*RH QUARTER GLASS	Cut	290.70 FL	*290.70 FL
18	1		*RHF DOOR GLASS OUTER MOULDING	Dented	65.00 FL	*65.00 FL
19	1		*RHF RIM	Dented	389.00 FL	*389.00 FL
20	1		*RHF TYRE	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,011.00	5,582.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,332.20	1,116.50
Total Parts (\$\$)	5,678.80	4,466.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR, RH SIDE MIRROR)	New	1,000.00	500.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR, RH SIDE MIRROR)	New	1,000.00	660.00
3	TO CHECK WIRING, FOCUS HEADLAMP	New	50.00	20.00
4	TO TUFF COAT	New	50.00	30.00
5	TO DO WHEEL ALIGNMENT	New	60.00	60.00
6	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	150.00	60.00
Gross Labour Cost (S\$)			2,310.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >