

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20007360/GVF3E2

**Date:** 02/10/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00000412001
Claimant Vehicle No :	SLM708G	Insured Vehicle No :	SGC985J
Date of Loss:	12/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202418/C02/LOWCT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM708G		
Make & Model:	HONDA CIVIC, 1.6 ESI (EG5) (M)	Engine No:	R16A15000036
Reg. Date:	26/08/2011 (Man. Year: 2009)	Chassis No:	JHMFD4520AS200028
Colour:	Grey	Odometer:	127325 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,534.33	4,190.89	8,343.44	66.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,980.00	870.00	30.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,384.33</b>	<b>6,170.89</b>	<b>9,213.44</b>	<b>59.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>(S\$)</b>	15,384.33	3,200.00	12,184.33	79.20
<b>+ GST 7.00/7.00% (S\$)</b>	1,076.90	224.00	852.90	79.20
<b>Nett Amount (S\$)</b>	<b>16,461.23</b>	<b>3,424.00</b>	<b>13,037.23</b>	<b>79.20</b>

### INSPECTION

Date of Assignment:	16/07/2020	
Date Inspected:	16/07/2020 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2020)
<b>Parts:</b>	144	HONDA CIVIC 1.6 ESI (EG5) (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM708G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS FRONT DOOR	Buckled	987.50 FL	*808.60 FL
2	1		*RHS FRONT DOOR HINGE	Not Necessary	48.42 FL	*- FL
3	1		*RHS FRONT DOOR CHROME	Scratched	143.06 FL	*107.00 FL
4	1		*RHS FRONT DOOR LOCK (2PCS)	Cut (1Pc Only)	318.42 FL	*250.00 FL
5	1		*RHS FRONT DOOR HANDLE (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*RHS FRONT DOOR OUTER MOULDING	Not Necessary	58.85 FL	*- FL
7	1		*RHS FRONT DOOR INNER TRIM BOARD	Cracked	343.20 FL	*343.20 FL
8	1		*RHS FRONT DOOR POWER WINDOW REGULATOR (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*RHS FRONT DOOR POWER WINDOW REGULATOR MOTOR	Not Necessary	612.75 FL	*- FL
10	1		*RHS REAR DOOR	Buckled	847.30 FL	*847.30 FL
11	1		*RHS REAR DOOR HINGE	Not Necessary	89.30 FL	*- FL
12	1		*RHS REAR DOOR LOCK	Not Necessary	318.42 FL	*- FL
13	1		*RHS REAR DOOR INNER TRIM BOARD	Cracked	365.53 FL	*365.53 FL
14	1		*RHS REAR DOOR CHROME	Cut	90.40 FL	*90.40 FL
15	1		*RHS REAR DOOR POWER WINDOW REGULATOR	Jammed	314.58 FL	*314.58 FL
16	1		*RHS REAR DOOR POWER WINDOW REGULATOR MOTOR	Not Necessary	615.38 FL	*- FL
17	1		*RHS REAR DOOR OUTER MOLDING	Cut	67.20 FL	*67.20 FL
18	1		*RHS REAR ABSORBER	Not Necessary	930.40 FL	*- FL
19	1		*RHS REAR LOWER ARM	Not Necessary	824.60 FL	*- FL
20	1		*RHS REAR UPPER ARM (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*RHS REAR CONTROL ARM	Not Necessary	730.40 FL	*- FL
22	1		*RHS REAR KNUCKLE }	Not Necessary	1,690.40 FL	*- FL
23	1		*RHS REAR KNUCKLE HUB }	Not Necessary	0.00 FL	*- FL
24	1		*RHS REAR WHEEL BEARING	Jammed	813.20 FL	*275.30 FL
25	1		*RHS REAR FENDER	Torn	2,560.40 FL	*1,482.00 FL
26	1		*RHS REAR FENDER SHIELD		79.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
27	1		*RHS REAR BUMPER	Not Necessary	825.20 FL	* - FL
28	1		*RHS REAR BUMPER RETAINER	Not Necessary	55.60 FL	* - FL
29	10		*REAR BUMPER CLIP	Not Necessary	50.00 FS	* - FS
30	10		*RHS REAR FENDER SHIELD CLIP	Necessary	50.00 FS	*30.00 FS
31	1		*RHS REAR RIM	Cut	900.00 FS	*200.00 FS
32	1		*RHS REAR TYRE	Not Necessary	450.00 FS	* - FS
33	10		*RHS FRONT INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	* - FS
34	10		*RHS REAR INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	* - FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **15,280.41** **5,181.11**  
**- List Item Discount on L Items 20.00/20.00% (\$\$)** 2,746.08 990.22

**Total Parts (\$\$)** **12,534.33** **4,190.89**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-	New	1,200.00	1,000.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	1,000.00	800.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	60.00	0.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	60.00
5	TO SUPPLY UNDER COATING / PUTTY ON PARTS REPLACED	New	50.00	0.00
6	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	120.00	0.00
7	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	80.00	0.00
8	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR	New	80.00	60.00
9	TO REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	New	80.00	0.00
10	CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	100.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,850.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >