

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jul 2020		17 Jul 2020 00:03 Edit Adj Rpt	S\$20,509.78 Edit Estimates	S\$20,509.78 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: -, Co. Reg. No.: -									
Main Claimant: LIM CHIN SHENG ALEX , ID: S1728621H									
Vehicle Reg. No.: SMC413Y		Date of Loss: 11/07/2020 03:00 - :59 [96 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202434/C02/LOWCT		Policy/Cover Note No.: SNM20D202434							
Vehicle Reg. No. (Insured): SMS112G		Policy No. (Claimant): GA370259							
		Excess: S\$0.00							
Repairer: Kang Auto Engineering Pte Ltd (HQ) BLK 14 SIN MING INDUSTRIAL ESTATE SECTOR B, #01-03, 575658 Sin Ming - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC413Y (SNM20D202434/C02/LOWCT)**
[SMS112G]

TP

LIM CHIN SHENG ALEX

Jul 11 2020 3:00AM

[-]

Kang Auto Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ☐

Video

1 per page ☐

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	14/07/20 19:21	Video - Accident [Linked Accident Report Documents]		Load MP4	

Assessment Reports

1 per page ☐

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/20 15:50	Adjuster Immediate Advice		Load HTM	
2	05/08/20 16:25	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/20 08:53	Accident Photo		Load JPG	☒
2	17/07/20 08:53	Accident Photo		Load JPG	☒
3	17/07/20 08:53	Accident Photo		Load JPG	☒
4	17/07/20 08:53	Accident Photo		Load JPG	☒
5	17/07/20 08:53	Accident Photo		Load JPG	☒
6	17/07/20 08:53	Accident Photo		Load JPG	☒
7	17/07/20 08:53	Accident Photo		Load JPG	☒
8	17/07/20 08:54	Accident Photo		Load JPG	☒
9	17/07/20 08:54	Accident Photo		Load JPG	☒
10	17/07/20 08:54	Accident Photo		Load JPG	☒
11	17/07/20 08:54	Accident Photo		Load JPG	☒
12	17/07/20 08:54	Accident Photo		Load JPG	☒
13	17/07/20 08:54	Accident Photo		Load JPG	☒
14	17/07/20 08:54	Accident Photo		Load JPG	☒
15	17/07/20 08:54	Accident Photo		Load JPG	☒
16	17/07/20 08:54	Accident Photo		Load JPG	☒
17	17/07/20 08:54	Accident Photo		Load JPG	☒
18	17/07/20 08:54	Accident Photo		Load JPG	☒
19	17/07/20 08:54	Accident Photo		Load JPG	☒
20	17/07/20 08:54	Accident Photo		Load JPG	☒
21	17/07/20 08:54	Accident Photo		Load JPG	☒
22	17/07/20 08:54	Accident Photo		Load JPG	☒
23	17/07/20 08:54	Accident Photo		Load JPG	☒
24	17/07/20 08:54	Accident Photo		Load JPG	☒
25	17/07/20 08:54	Accident Photo		Load JPG	☒
26	17/07/20 08:54	Accident Photo		Load JPG	☒
27	17/07/20 08:54	Accident Photo		Load JPG	☒
28	17/07/20 08:54	Accident Photo		Load JPG	☒
29	17/07/20 08:54	Accident Photo		Load JPG	☒
30	17/07/20 08:54	Accident Photo		Load JPG	☒

Documentation

1 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
----	-----------------	-----------------------------------	--	-----------	-------

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	06/08/20 15:08	LETTER	 Load PDF	
2	06/08/20 15:34	LTA REBATE	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/07/20 19:21	Video - Accident	 Load MP4	

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/07/20 19:28	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/07/20 19:23	Accident Photo	 Load JPG	☒
2	14/07/20 19:23	Accident Photo	 Load JPG	☒
3	14/07/20 19:23	Accident Photo	 Load JPG	☒
4	14/07/20 19:23	Accident Photo	 Load JPG	☒
5	14/07/20 19:23	Accident Photo	 Load JPG	☒
6	14/07/20 19:23	Accident Photo	 Load JPG	☒
7	14/07/20 19:23	Accident Photo	 Load JPG	☒
8	14/07/20 19:23	Accident Photo	 Load JPG	☒
9	14/07/20 19:23	Accident Photo	 Load JPG	☒
10	14/07/20 19:23	Accident Photo	 Load JPG	☒
11	14/07/20 19:23	Accident Photo	 Load JPG	☒
12	14/07/20 19:23	Accident Photo	 Load JPG	☒
13	14/07/20 19:23	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/07/20 15:39	Sketch Plan	 Load TIF	
2	14/07/20 15:39	Sketch Plan #2	 Load TIF	
3	14/07/20 15:39	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20007361/KSF3S2**Date:** 06/08/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: SNM20D202434

Claimant Vehicle No : SMC413Y **Insured Vehicle No :** SMS112G

Date of Loss: 11/07/2020 Nature of Claim: TP Claim No: SNM20D202434/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC413Y**

Make & Model: MERCEDES-BENZ CLS350, 3.5 (A) Engine No: 27695230070385

Reg. Date: 28/06/2012 (Man. Year: 2011) Chassis No: WDD2183592A032560

Colour: Metallic Black Odometer: 92218 km

Engine Capacity: 3498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35 R19

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,375.85	17,939.78	14,436.07	44.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	2,570.00	4,500.00	63.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	39,445.85	20,509.78	18,936.07	48.01

INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 16/07/2020 Inspected At: Kang Auto Engineering Pte Ltd
160 SIN MING DRIVE #02-16
SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

The total amount incurred will be Market Value \$ 80,000.00 minus Total Rebate \$ 61,958.00 = \$ 18,042.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$14,094.90 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2020)
Parts:	143	MERCEDES-BENZ CLS350 3.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC413Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET LOCK	Repair	246.70 FL	*- FL
2	1		*FRONT BUMPER	Bent	1,107.80 FL	*1,107.80 FL
3	1		*FRONT BUMPER BADGE	Necessary	145.60 FL	*145.60 FL
4	1		*FRONT BUMPER GRILLE	Cracked	376.60 FL	*376.60 FL
5	1		*FRONT BUMPER GRILLE BADGE	*Check	48.60 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	58.60 FL	*58.60 FL
7	1		*FRONT BUMPER LOWER GRILLE	Cracked	210.70 FL	*210.70 FL
8	1		*FRONT BUMPER O/S SIGNAL LAMP	Broken	208.10 FL	*208.10 FL
9	1		*FRONT BUMPER TOWING COVER	Missing	61.20 FL	*61.20 FL
10	1		*FRONT BUMPER SIDE RETAINER	Distorted	72.80 FL	*72.80 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	386.70 FL	*386.70 FL
12	1		*FRONT BUMPER BRACKETS	O/s Bent	216.20 FL	*108.10 FL
13	1		*FRONT BUMPER ENGINE DUST COVER	Missing	486.50 FL	*486.50 FL
14	2		*FRONT BUMPER CHROME	Necessary	249.20 FL	*249.20 FL
15	1		*HEADLAMP ASSY	O/s Broken	7,430.00 FL	*3,715.60 FL
16	1		*HEADLAMP BRACKET R/H	O/s Bent	373.60 FL	*186.80 FL
17	1		*FRONT APRON PANEL	*Check	240.60 FL	*- FL
18	1		*FRONT SUPPORT PANEL (CENTRE)	*Check	590.80 FL	*- FL
19	1		*FRONT R/H FENDER	Buckled	1,080.60 FL	*1,080.60 FL
20	1		*FRONT R/H FENDER INNER SHIELD COVER	Torn	167.80 FL	*167.80 FL
21	1		*AIR CLEANER IN-TAKE HOUSE	*Check	385.80 FL	*- FL
22	1		*RADIATOR ASSY	*Check	1,080.90 FL	*- FL
23	1		*RADIATOR AUTO FAN ASSY	*Check	870.60 FL	*- FL
24	1		*RADIATOR HOSE	*Check	250.90 FL	*- FL
25	1		*AIR CON CONDENSER	*Check	1,750.90 FL	*- FL
26	1		*AIR CON COMPRESSOR	*Check	2,560.40 FL	*- FL
27	1		*AIR CON COOLING PIPE (ALUMINIUM)	*Check	390.10 FL	*- FL
28	1		*AIR CON DISCHARGE PIPE	*Check	180.90 FL	*- FL
29	1		*AIR CON SUCTION PIPE	*Check	210.80 FL	*- FL
30	1		*REAR BUMPER	Torn	1,250.90 FL	*1,250.90 FL
31	1		*REAR BUMPER MOULDING	Necessary	270.80 FL	*270.80 FL
32	1		*REAR BUMPER LOWER LID	Missing	320.40 FL	*320.40 FL
33	1		*REAR BUMPER BRACKETS	O/s Bent	216.40 FL	*108.20 FL
34	1		*REAR BUMPER REINFORCEMENT	Bent	489.90 FL	*489.90 FL
35	1		*REAR BUMPER INNER GRILLE	*Check	107.20 FL	*- FL
36	1		*SET REAR BUMPER CLIPS	Necessary	58.60 FL	*58.60 FL
37	1		*REAR BUMPER SIDE RETAINER	Cracked	84.60 FL	*84.60 FL
38	1		*TAILLAMP ASSY (RH)	Broken	710.00 FL	*710.00 FL
39	1		*REAR EXHAUST SILENCER	Bent	2,860.80 FL	*2,860.80 FL
40	1		*REAR EXHAUST COVER	Bent	386.70 FL	*386.70 FL
41	1		*REAR EXHAUST MUDFLAG	Torn	146.70 FL	*146.70 FL
42	1		*SET FRONT SENSORS	*Check	650.00 FS	*- FS
43	1		*SET REAR BUMPER SENSOR	Torn	650.00 FS	*650.00 FS
44	1		*SET REVERSE SENSOR	*Check	400.00 FS	*- FS
45	1		*FRONT & REAR RH TYRES (@ \$1200.00 DISC 50%)	Rear Cut	1,200.00 FS	*300.00 FS
46	1		*SET FRONT & REAR RH TYRE RIMS	Dented	2,400.00 FS	*2,400.00 FS

Report was unsubmitted during this print-out.

8/6/2020				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT & REAR NUMBER PLATE	Frnt Bent	150.00 FS	*45.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	33,793.00	18,705.30
				- List Item Discount on L Items 5.00/5.00% (\$)	1,417.15	765.52
				Total Parts (\$)	32,375.85	17,939.78
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE. (*Check)	New	150.00	0.00
2	TO CHECK WIRING.	New	50.00	40.00
3	TO RE-SET ENGINE. (*Check)	New	350.00	0.00
4	TO REMOVE & REFIT REAR WINDSCREEN.	New	250.00	0.00
5	TO REMOVE & REFIT AIR CON CONDENSER & TOP UP GAS. (*Check)	New	180.00	0.00
6	TO REMOVE & REFIT EXHAUST SILENCER.	New	250.00	80.00
7	TO RESET WHEEL ALIGNMENT.	New	180.00	120.00
8	TO APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.	New	160.00	30.00
9	TO PUTTY AND SPRAY PAINT.	New	2,500.00	1,200.00
10	LABOUR CHARGES.	New	3,000.00	1,100.00
Gross Labour Cost (\$\$)			7,070.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >