



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2006874  
INV Date 07/10/2020  
Reference CC3/CTI20007362/Qes3s2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 5344U  
Insured Veh. GBJ 6651E  
Claim No. SNM20D202262  
Policy No. DMCVSN1927871900  
Accident Date 25/06/2020  
Inspection Date 25/06/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI20007362/Qes3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 07-10-2020		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 6651E	Veh. Inspected	SHB 5344U	
Policy No.	DMCVSN1927871900	Coverage (\$)	0.00	
Claim No.	SNM20D202262	Excess (\$)	0.00	
Assign From		Assign Date	25/06/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU903575517	Colour	MAROON	
Odometer	246815	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ATREZZO	6 mm	
L/H Front Tyre	195/65 R15	ATREZZO	6 mm	
R/H Rear Tyre	195/65 R15	ATREZZO	6 mm	
L/H Rear Tyre	195/65 R15	ATREZZO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/06/2020	Inspection Date	25/06/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5344U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	RETAINER, RR BUMPER, LH (DISC 25%)	BROKEN	111.50	83.63
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CRUSHED	558.30	418.73
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	CRUSHED	222.60	166.95
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	DENTED	929.60	697.20
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	CRUSHED	891.20	668.40
1	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE (DISC 25%)	NECESSARY	27.90	20.93
1	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR (DISC 25%)	BROKEN	725.90	544.43
1	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE (DISC 25%)	NECESSARY	27.90	20.93
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH (DISC 25%)	NECESSARY	29.90	22.43
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH (DISC 25%)	NECESSARY	29.90	22.43
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.78
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	COVER, RR BUMPER ASSY (DISC 25%)	CRUSHED	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
1	FILLER, RR BUMPER, LH (DISC 25%)	CUT	119.90	89.93
1	TAILGATE WEATHERSTRIP, BACK (DISC 25%) (ADDITIONAL)	CRUSHED	360.70	270.53
1	END PANEL, COVER, DECK TRIM SERVICE (DISC 25%) (ADDITIONAL)	CRUSHED	47.00	35.25

Report Ref No. CC3/CTI20007362/Qes3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL, COVER, DECK TRIM, REAR (DISC 25%) (ADDITIONAL)	CRUSHED	122.80	92.10
1	LENS & BODY, REAR COMBINATION LAMP, LH (DISC 10%)	CRUSHED	438.10	394.29
1	LAMP SET, STOP CENTER (DISC 10%) (ADDITIONAL)	CRACKED	186.50	167.85
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @ \$37.00 (SN)	NECESSARY	111.00	111.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
2	STOPPER, RR BUMPER, RH & LH @ \$4.30	SERVICEABLE	8.60	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	14.80	-
3	PAD, RR BUMPER, CTR @ \$2.20	SERVICEABLE	6.60	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-
1	LENS & BODY ASSY, RR BUMPER, LH	SERVICEABLE	486.80	-
1	WIRE, LUGGAGE ROOM	SERVICEABLE	143.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
2	TAIL GATE BACK DOOR HINGE ASSY, RH & LH @ \$59.10	SERVICEABLE	118.20	-
2	TAIL GATE BOLT, BACK DOOR STAY, RH & LH @ \$11.80	SERVICEABLE	23.60	-
1	TAIL GATE LOCK ASSY, BACK DOOR	SERVICEABLE	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	SERVICEABLE	25.30	-
1	TAIL GATE STAY ASSY, BACK DOOR, LH	SERVICEABLE	235.00	-
1	TAIL GATE STAY ASSY, BACK DOOR, RH	SERVICEABLE	235.00	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	SERVICEABLE	24.90	-
1	TAIL GATE GLASS SUB-ASSY, BACK DOOR	SERVICEABLE	1,569.70	-
1	TAIL GATE WEATHERSTRIP, BACK DOOR	SERVICEABLE	360.70	-
1	TAILGATE BOARD, COVER	SERVICEABLE	24.10	-
1	TAILGATE BOARD, HANDLE FULL	SERVICEABLE	19.50	-
1	TAILGATE BOARD ASSY	SERVICEABLE	251.50	-
1	TAILGATE TRIM, LH	SERVICEABLE	92.10	-
1	TAILGATE TRIM, LOWER	SERVICEABLE	218.50	-
1	NUMBER PLATE	SERVICEABLE	35.00	-

Report Ref No. CC3/CTI20007362/Qes3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	NUMBER PLATE FRAME	SERVICEABLE	25.00	-
1	LAMP ASSY, LICENSE PLATE	SERVICEABLE	127.40	-
1	CAMERA REAR ASSY, TELEVISION	SERVICEABLE	1,103.80	-
1	SWITCH ASSY, BACK DOOR OPENER	SERVICEABLE	149.40	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LAMP SET, STOP CENTER	SERVICEABLE	186.50	-
1	COVER, REAR COMBINATION LAMP, RH	SERVICEABLE	54.00	-
1	END PANEL SUBASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	END PANEL, COVER DECK TRIM SERVICE HOLE	SERVICEABLE	47.00	-
1	END PANEL, COVER, DECK TRIM REAR	SERVICEABLE	122.80	-
1	REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	SERVICEABLE	56.70	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	SPARE TYRE PANEL, PAN REAR FLOOR	SERVICEABLE	564.80	-
1	EXTENSION, REAR FLOOR SIDE PANEL, LH	SERVICEABLE	76.20	-
1	BOARD, REAR FLOOR, NO.1	SERVICEABLE	502.20	-
1	BOX DECK FLOOR, LH	SERVICEABLE	303.40	-
1	DUCT ASSY, QUARTER VENT, RH & LH	SERVICEABLE	65.00	-
1	LINER, REAR FENDER, LH	SERVICEABLE	135.80	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
2	SEAL, RR BUMPER ARM, RH & LH @ \$11.00	SERVICEABLE	22.00	-
2	REAR BUMPER GROMMET SCREW @ \$2.20	SERVICEABLE	4.40	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	SPOILER SUB-ASSY, REAR	TO REPAIR SEE LABOUR	1,322.10	-
1	TROUGH, BACK DOOR, LH	TO REPAIR SEE LABOUR	99.80	-
1	PANEL SUB-ASSY, FENDER REAR LH	TO REPAIR SEE LABOUR	824.80	-
1	SOLAR FILM (SN)	NECESSARY	475.00	125.00
			19,038.90	4,814.76
	<b>LABOUR</b>			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF SPOILER SUB-ASSY, REAR; TROUGH, BACK DOOR, LH AND PANEL SUB-ASSY, FENDER REAR LH.		1,902.00	800.00

Report Ref No. CC3/CTI20007362/Qes3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		3,114.00	1,110.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	100.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	250.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,326.00	2,180.00
<b>GRAND TOTAL</b>			<b>25,364.90</b>	<b>6,994.76</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,994.76</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/CTI20007362/Qes3s2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.