

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007367/T1PS3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900255580

Claimant
Vehicle No : SHC1150H **Insured Vehicle No :** SMR8822T

Date of Loss: 16/07/2020 Nature of Claim: TP Claim No: 2056257084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1150H		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS060857
Reg. Date:	10/08/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU603563227
Colour:	Blue	Odometer:	539083 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,796.85	139.87	1,656.98	92.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	770.00	350.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,916.85	909.87	2,006.98	68.81
+ GST 7.00/7.00% (\$\$)	204.18	63.69	140.49	68.81
Nett Amount (\$\$)	3,121.03	973.56	2,147.47	68.81
+ Loss of Use (1.5 x S\$50.00/day) (\$\$)		75.00		
+ Car Rental (1.5 x S\$125.40/day) (\$\$)		188.10		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		1,244.15		
Global Sum Settlement (\$\$)		1,200.00		

INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 16/07/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY FRONT RH	Repair	945.30 FL	* - FL
2	1		*PANEL SUB-ASSY FRONT DOOR	Repair	1,264.00 FL	* - FL
3	1		*FRT DOOR LOGO SONATA CTPL	Necessary	75.00 FS	*75.00 FS
4	1		*EMBLEM GRILLE PANEL	Necessary	86.50 FL	*86.50 FL
					Sub Total (S\$)	2,370.80
					- List Item Discount on L Items 25.00/25.00% (S\$)	161.50
						573.95
					Total Parts (S\$)	139.87

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	600.00	450.00
3	TRANSFER DOOR PARTS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,120.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >