

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007370/R1KS3Q2

Date: 24/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993968

Claimant Vehicle No : SJP1976A **Insured Vehicle No :** SLL8107T

Date of Loss: 15/07/2020 Nature of Claim: TP Claim No: 8089781890SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP1976A	Engine No:	DED015086
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI (A)	Chassis No:	WVWZZZ7NZJV002805
Reg. Date:	31/10/2017 (Man. Year: 2017)	Odometer:	50045 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,687.08	21,909.82	8,777.26	28.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	27,790.00	16,190.00	11,600.00	41.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	58,477.08	38,099.82	20,377.26	34.85
+ GST 7.00/7.00% (S\$)	4,093.40	2,666.99	1,426.41	34.85
Nett Amount (S\$)	62,570.48	40,766.81	21,803.67	34.85
+ Car Rental (20.0 x S\$110.00/day + 7.00% GST) (S\$)		2,354.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		43,128.26		
Global Sum Settlement (S\$)		43,100.00		

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 20/07/2020 Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 18.0 days

Adjuster: MOHD RASUL

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD: FRT BONNET	Bent	1,595.18 FS	*1,595.18 FS
2	1		*FLAP HINGE: LH	Serviceable	164.25 FS	*- FS
3	1		*FLAP HINGE: RH	Serviceable	164.25 FS	*- FS
4	1		*JOUNCE BUMPER: STOP BUFFER	Necessary	19.82 FS	*19.82 FS
5	1		*HOOK: LATCH	Bent	89.37 FS	*89.37 FS
6	1		*HOOD LATCH LOWER PORTION: BONNET LOCK	Bent	135.59 FS	*135.59 FS
7	1		*HOOD SILENCER: BONNET INSULATOR	Deformed	265.93 FS	*265.93 FS
8	1		*COVER FOR BUMPER PRIMED	Deformed	1,620.73 FS	*1,620.73 FS
9	1		*BUMPER BRACKET: FRT REINFORCEMENT	Bent	764.09 FS	*764.09 FS
10	1		*GUIDE PIECE: BUMPER CENTRE BRACKET	Cracked	142.12 FS	*142.12 FS
11	1		*GUIDE PIECE: BUMPER SIDE BRACKET LH	Necessary	32.35 FS	*32.35 FS
12	1		*GUIDE PIECE: BUMPER SIDE BRACKET RH	Serviceable	32.35 FS	*- FS
13	1		*SUPPORT PART: BUMPER INNER BRACKET LH	Serviceable	27.86 FS	*- FS
14	1		*GRILL SATIN BLACK: BUMPER CENTRE LOWER GRILLE	Cracked	180.49 FS	*180.49 FS
15	1		*DECORATIVE MOULDING BRIGH: CTR LOWER GRILLE CHROM	Cracked	209.71 FS	*209.71 FS
16	1		*COOLING AIR GRILL SATIN B: FOG LAMP GRILLE LH	Deformed	173.48 FS	*173.48 FS
17	1		*COOLING AIR GRILL SATIN B: FOG LAMP GRILLE RH	Serviceable	173.48 FS	*- FS
18	1		*CAP PRIMED: TOWING CAP	Deformed	56.24 FS	*56.24 FS
19	2		*SENSOR PRIMED: FRT BUMPER PARKING SENSOR	Not Working	344.66 FS	*344.66 FS
20	2		*SEAL RING SATIN BLACK	Necessary	1.52 FS	*1.52 FS
21	1		*PRESSURE CYLINDER: LH	Serviceable	182.92 FS	*- FS
22	1		*JET CARRIER WITH JET: LH	Serviceable	43.78 FS	*- FS
23	5		*HOSE IN COILS OF 5M ORDE	Serviceable	146.15 FS	*- FS
24	1		*HARNESS FOR ULTRASONIC SE: FRT SENSOR WIRE HARNESS	Slightly bent	111.41 FS	*- FS
25	1		*RADIATOR GRILLE SATIN BLA	Cracked	644.08 FS	*644.08 FS
26	1		*VW SIGN BLACK HIGH GLOSS	Necessary	112.51 FS	*112.51 FS
27	1		*HEADLAMPS FOR CURVE LIGHT: RH	Cracked	2,242.27 FS	*2,242.27 FS
28	1		*HEADLAMPS FOR CURVE LIGHT: LH	Cracked	2,242.27 FS	*2,242.27 FS
29	1		*CONTROL UNIT FOR CORNERIN	Not Working	601.96 FS	*601.96 FS
30	1		*BALLAST FOR GAS DISCHARGE	Serviceable	791.96 FS	*- FS
31	1		*POWER MODULE FOR DAY DRIV	Serviceable	392.42 FS	*- FS
32	1		*FLAST CONTACT HOUSING WITH: H/LAMP WIRE HOUSING	Cracked 1pc Only	36.86 FS	*18.43 FS
33	1		*HALOGEN FOG LIGHTS WITH S: FOG LAMP LH	Serviceable	302.49 FS	*- FS
34	1		*LOCK CARRIER WITH MOUNTIN	Cracked	958.59 FS	*958.59 FS
35	1		*SUPPORT FOR LOCK CARRIER	Cracked	112.38 FS	*112.38 FS
36	1		*CROSS SUPPORT: H/LAMP TOP PANEL LH	Cracked	56.02 FS	*56.02 FS
37	1		*CROSS SUPPORT: H/LAMP TOP PANEL RH	Bent	56.02 FS	*56.02 FS
38	1		*REFRIGERANT CONDENSER WIT: A/C CONDENSER	Bent	813.87 FS	*813.87 FS
39	1		*RADIATOR	Serviceable	868.14 FS	*- FS
40	1		*WATER HOSE WITH QUICK COU: RADIATOR TOP HOSE	Serviceable	167.39 FS	*- FS
41	2		*COOLANT CONCERNTRATE	Necessary	84.98 FS	*84.98 FS
42	1		*BRACKET: RADIATOR BRACKET	Serviceable	30.16 FS	*- FS
43	1		*AIR DUCT: AIR GUIDE RH	Serviceable	43.49 FS	*- FS
44	1		*AIR DUCT: AIR GUIDE LH	Cracked	43.49 FS	*43.49 FS
45	1		*DUAL FAN COWL	Serviceable	236.19 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*ELECTRIC FAN	Serviceable	774.72 FS	*- FS
47	1		*COVER: AIR INTAKE TOP COVER	Serviceable	27.94 FS	*- FS
48	1		*AIR DUCT: AIR INTAKE TOP HOUSING	Cracked	57.53 FS	*57.53 FS
49	1		*AIR DUCT: AIR INTAKE CENTRE HOUSING	Cracked	32.99 FS	*32.99 FS
50	1		*AIR DUCT: AIR INTAKE LOWER HOUSING	Cracked	37.20 FS	*37.20 FS
51	1		*AIR CLEANER	Serviceable	309.88 FS	*- FS
52	1		*BATTERY TRAY: BATTERY BRACKET	Serviceable	68.96 FS	*- FS
53	1		*WASH WATER RESERVOIR: WIPER TANK	Serviceable	152.86 FS	*- FS
54	1		*GASKET	Not Necessary	1.95 FS	*- FS
55	1		*GASKET	Not Necessary	4.70 FS	*- FS
56	1		*WINDSHIELD CLEANER CONCEN	Not Necessary	15.71 FS	*- FS
57	1		*FENDER: LH	Bent	791.78 FS	*791.78 FS
58	1		*CROSS SUPPORT: FENDER BRACKET LH	Necessary	40.10 FS	*40.10 FS
59	1		*REAR TRUNK LID	Bent	2,680.27 FS	*2,680.27 FS
60	2		*1K WINDOW ADHESIVE	Necessary	99.02 FS	*99.02 FS
61	1		*ALL PURPOSE CLEANER	Necessary	89.22 FS	*89.22 FS
62	1		*PRIMER	Necessary	25.74 FS	*25.74 FS
63	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.77 FS	*23.77 FS
64	2		*APPLICATOR	Necessary	18.78 FS	*18.78 FS
65	1		*PACKING ADHESIVE: RR NUMBER PLATE PACKING	Necessary	27.82 FS	*27.82 FS
66	4		*RIVETTED CAP NUT	Necessary	8.92 FS	*8.92 FS
67	1		*HOO LATCH: LIC LOCK	Serviceable	867.54 FS	*- FS
68	1		*VW SIGN BLACK HIGH GLOSS	Necessary	113.71 FS	*113.71 FS
69	1		*INSCRIPTION CHROME: NAME PLATE - SHARAN	Necessary	85.53 FS	*85.53 FS
70	1		*INSCRIPTION BRIGHT CHROME: NAME PLATE - 380 TSI	Necessary	70.04 FS	*70.04 FS
71	1		*ADDITIONAL BRAKE LIGHT WI: 3RD BRAKE LIGHT	Necessary	213.11 FS	*213.11 FS
72	1		*LED TAIL LIGHT WITH REAR: TAILLIGHT INNER RH	Serviceable	568.85 FS	*- FS
73	1		*COVER FOR BUMPER PRIMED: REAR BUMPER	Deformed	1,250.67 FS	*1,250.67 FS
74	1		*SPOILER SATIN BLACK	Deformed	257.35 FS	*257.35 FS
75	1		*BUMPER BRACKET: REAR REINFORCEMENT	Bent	755.41 FS	*755.41 FS
76	1		*ATTACHEMENT STRIP: RR BUMPER CENTRE BRACKET	Serviceable	181.89 FS	*- FS
77	1		*GUIDE PIECE: BUMPER SIDE BRACKET LH	Serviceable	78.52 FS	*- FS
78	1		*GUIDE PIECE: BUMPER SIDE BRACKET RH	Serviceable	78.52 FS	*- FS
79	3		*SENSOR PRIMED: REAR BUMPER PARKING SENSOR	Serviceable	516.99 FS	*- FS
80	3		*SEAL RING SATIN BLACK	Necessary	2.28 FS	*2.28 FS
81	1		*REFLECTOR: RH	Broken	64.85 FS	*64.85 FS
82	1		*EXHAUST SILENCER REAR	Serviceable	1,076.61 FS	*- FS
83	1		*DUAL CAMP	Serviceable	59.35 FS	*- FS
84	1		*HEAT SHIELD FOR EXHAUST M: REAR SILENCER HEAT SHIELD	Bent	220.77 FS	*220.77 FS
85	1		*UNDERBODY LINING: REAR BUMPER LOWER COVER LH	Serviceable	95.15 FS	*- FS
86	1		*UNDERBODY LINING: RR BUMPER LOWER COVER RH	Deformed	106.71 FS	*106.71 FS
87	1		*WHEELHOUSE LINER: RR FENDER LINER RH	Deformed	138.49 FS	*138.49 FS
88	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
89	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
90	1		*STICKER	Necessary	13.99 FS	*13.99 FS
91	1		*STICKER AC REFRIGERAN	Necessary	16.43 FS	*16.43 FS
92	1		*STICKER OVERFILLED ENGINE	Necessary	13.99 FS	*13.99 FS
93	1		*REAR REINFORCEMENT FOAM	Cracked	129.26 FS	*129.26 FS
94	1		*REAR TOWING COVER	Deformed	69.55 FS	*69.55 FS
95	1		*NOZZLE CYLINDER JOINT	Cut	15.65 FS	*15.65 FS
96	1		*EXHAUST SILENCER FRONT	Bent	660.74 FS	*660.74 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					30,687.08	21,909.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING.	New	480.00	480.00
3	LEAKED CHECK, VACUUM & REGAS.	New	420.00	420.00
4	A/C GAS.	New	60.00	60.00
5	LABOUR FRT.	New	6,720.00	3,360.00
6	SPRAY PAINT FRT.	New	4,800.00	3,200.00
7	LABOUR REAR.	New	5,880.00	2,520.00
8	SPRAY PAINT REAR.	New	4,800.00	3,200.00
9	R&R REAR W/SCREEN.	New	840.00	840.00
10	TRANSFER BOOT LID MECHANISM.	New	840.00	420.00
11	R&R REAR EXHAUST PIPE.	New	840.00	420.00
12	R&R REAR LUGGAGE TRIM.	New	840.00	420.00
13	R&R REAR SEAT.	New	840.00	420.00
14	CHECK REAR WATER LEAK.	New	150.00	150.00
Gross Labour Cost (\$\$)			27,790.00	16,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >