

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20007374/KEA3Q2

**Date:** 08/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700084839

**Claimant**  
**Vehicle No :** SMQ4512U **Insured Vehicle No :** SLU4209L

Date of Loss: 16/07/2020 Nature of Claim: TP Claim No: 1047335645SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMQ4512U</b>		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR2B81364
Reg. Date:	18/11/2019 (Man. Year: 2018)	Chassis No:	ZYX102148341
Colour:	Metallic White/Red	Odometer:	13384 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,900.62	1,993.69	906.93	31.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,050.00	800.00	43.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,750.62</b>	<b>3,043.69</b>	<b>1,706.93</b>	<b>35.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>(S\$)</b>	4,750.62	2,400.00	2,350.62	49.48
<b>+ GST 7.00/7.00% (S\$)</b>	332.54	168.00	164.54	49.48
<b>Nett Amount (S\$)</b>	<b>5,083.16</b>	<b>2,568.00</b>	<b>2,515.16</b>	<b>49.48</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,070.00</b>		

### INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 17/07/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,020.30 FL	*1,020.30 FL
2	1		*REAR TAILGATE CHR EMBLEM	Not Necessary	58.60 FL	*- FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	93.60 FL	*- FL
4	1		*REAR TAILGATE EMBLEM	Not Necessary	62.50 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	55.30 FL	*55.30 FL
6	12		*REAR TAILGATE INNER TRIM CLIPS	Serviceable	74.40 FL	*- FL
7	1		*REAR BUMPER	Buckled	1,128.00 FL	*550.82 FL
8	10		*REAR BUMPER CLIPS	Necessary	58.00 FL	*58.00 FL
9	1		*REAR BUMPER LIP COVER	Dented / Cracked	496.80 FL	*398.00 FL
10	1		*REAR BUMPER LIP FIXING COVER	Serviceable	38.20 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	661.80 FL	*482.50 FL
12	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
13	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
14	2		*REAR WINDSCREEN LOWER STOPPER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,837.50</b>	<b>2,634.92</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	936.88	641.23
<b>Total Parts (\$\$)</b>	<b>2,900.62</b>	<b>1,993.69</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	600.00	400.00
2	LABOUR CHARGES TO REMOVE ,REPLACE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC .TO EFFECT REPLACE OF REAR BUMPER	New	100.00	50.00
4	LABOUR CHARGES TO DISMANTLE & REASSEMBLE REAR TAILGATE INNER MECHANISM & ETC .TO EFFECT REPLCAE OF REAR TAILGATE	New	120.00	60.00
5	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	800.00	400.00
6	TO CHECK & WIRING & ELECTRICAL WIRING SYSTEM	New	80.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>1,850.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >