Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20007378/KPA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2019-00000959

Claimant CUD51001 Inquired Vehicle No. 1997

Vehicle No: SHD5199L Insured Vehicle No: SKQ1868L

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: 1202000018995

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD5199L

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B72079

Reg. Date: 01/11/2018 (Man. Year: 2018) Chassis No: JTDKB3FU103076615

Colour: White Odometer: 168674 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm
Front Right Side: Sailun 8 mm
Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,665.32	1,145.32	2,520.00	68.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,060.00	750.00	9,310.00	92.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,725.32	1,895.32	11,830.00	86.19
+ GST 7.00/7.00% (S\$)	960.77	132.67	828.10	86.19
Nett Amount (S\$)	14,686.09	2,027.99	12,658.10	86.19

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 16/07/2020 Inspected At: Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2020)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5199L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Repair	1,300.70 FL	*- FL
1		*TAPE,BLACK OUT,NO.1 FRT LH	Not Necessary	13.30 FL	*- FL
1		*TAPE,BLACK OUT,NO.2 FRT LH	Not Necessary	43.50 FL	*- FL
1		*TAPE,BLACK OUT,NO.3 FRT LH	Not Necessary	26.30 FL	*- FL
1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Bent	1,294.90 FL	*1,294.90 FL
1		*LOCK ASSY ,REAR DOOR WITH MOTOR ,LH	Repair	561.90 FL	*- FL
1		*HING ASSY ,REAR DOOR ,UPPER LH	Serviceable	98.90 FL	*- FL
1		*HING ASSY ,REAR DOOR ,LOWER LH	Serviceable	87.10 FL	*- FL
1		*CHECK ASSY ,REAR DOOR ,LH	Serviceable	183.80 FL	*- FL
1		*MOULDING ASSY ,REAR DOOR BELT ,LH	Serviceable	113.50 FL	*- FL
1		*WEATHERSTRIP ,REAR DOOR ,NO.3 LH	Serviceable	36.20 FL	*- FL
1		*TAPE ,BLACK OUT ,NO.1 REAR LH	Necessary	21.90 FL	*21.90 FL
1		*TAPE ,BLACK OUT ,NO.2 REAR LH	Necessary	34.90 FL	*34.90 FL
1		*TAPE ,BLACK OUT ,NO.3 REAR LH	Necessary	15.40 FL	*15.40 FL
1		*MOULDING ASSY ,BODY ROCKER PANEL LH	Repair	594.80 FL	*- FL
1		*FRONT DOOR STICKER TRANS-CAB	Necessary	100.00 FS	*60.00 FS
1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
1		*SET ROCKER PANEL MOULDING CLIP	Not Necessary	55.00 FS	*- FS
1		*DOOR HINGE SCREW	Not Necessary	45.00 FS	*- FS
1		*DOOR CHECK SCREW	Not Necessary	45.00 FS	*- FS
nchise	part. S=Spc	Nett. L=ListItemDisc.		,	
			Sub Total (S\$)	4,772.10	1,487.10
		- List Itam Discount on Liltams 2	5 00/25 00% (S\$)	1,106.78	341.78
		- List item Discount on Littems 2	0.00/20.00 /0 (Oψ)	1,100.70	041.70
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*PANEL SUB-ASSY ,FRONT DOOR ,LH *TAPE,BLACK OUT,NO.1 FRT LH *TAPE,BLACK OUT,NO.2 FRT LH *TAPE,BLACK OUT,NO.3 FRT LH *TAPE,BLACK OUT,NO.3 FRT LH *PANEL SUB-ASSY ,REAR DOOR ,LH *LOCK ASSY ,REAR DOOR WITH MOTOR ,LH *HING ASSY ,REAR DOOR ,LOWER LH *HING ASSY ,REAR DOOR ,LOWER LH *MOULDING ASSY ,REAR DOOR ,BELT ,LH *WEATHERSTRIP ,REAR DOOR ,NO.3 LH *TAPE ,BLACK OUT ,NO.1 REAR LH *TAPE ,BLACK OUT ,NO.2 REAR LH *TAPE ,BLACK OUT ,NO.3 REAR LH *TAPE ,BLACK OUT ,NO.3 REAR LH *TAPE ,BLACK OUT ,NO.3 REAR LH *FRONT DOOR STICKER TRANS-CAB *REAR DOOR STICKER TRANS-CAB *REAR DOOR STICKER 6555-3333 *SET ROCKER PANEL MOULDING CLIP *DOOR HINGE SCREW *DOOR CHECK SCREW anchise part. S=SpcNett. L=ListitemDisc.	1 *PANEL SUB-ASSY ,FRONT DOOR ,LH Repair 1 *TAPE,BLACK OUT,NO.1 FRT LH Not Necessary 1 *TAPE,BLACK OUT,NO.2 FRT LH Not Necessary 1 *TAPE,BLACK OUT,NO.3 FRT LH Not Necessary 1 *PANEL SUB-ASSY ,REAR DOOR ,LH Bent 1 *LOCK ASSY ,REAR DOOR ,UH Repair 1 *HING ASSY ,REAR DOOR ,UPPER LH Serviceable 1 *HING ASSY ,REAR DOOR ,LOWER LH Serviceable 1 *CHECK ASSY ,REAR DOOR ,LOWER LH Serviceable 1 *CHECK ASSY ,REAR DOOR ,LH Serviceable 1 *MOULDING ASSY ,REAR DOOR BELT ,LH Serviceable 1 *WEATHERSTRIP ,REAR DOOR ,NO.3 LH Serviceable 1 *TAPE ,BLACK OUT ,NO.1 REAR LH Necessary 1 *TAPE ,BLACK OUT ,NO.2 REAR LH Necessary 1 *TAPE ,BLACK OUT ,NO.3 REAR LH Necessary 1 *TAPE ,BLACK OUT ,NO.3 REAR LH Repair 1 *FRONT DOOR STICKER TRANS-CAB Necessary 1 *REAR DOOR STICKER 6555-3333 Necessary 1 *SET ROCKER PANEL MOULDING CLIP Not Necessary 1 *DOOR HINGE SCREW Not Necessary 1 *DOOR CHECK SCREW Not Necessary 1 *DOOR CHECK SCREW Not Necessary	1 *PANEL SUB-ASSY ,FRONT DOOR ,LH Repair 1,300.70 FL 1 *TAPE,BLACK OUT,NO.1 FRT LH Not Necessary 13.30 FL 1 *TAPE,BLACK OUT,NO.2 FRT LH Not Necessary 26.30 FL 1 *TAPE,BLACK OUT,NO.3 FRT LH Not Necessary 26.30 FL 1 *PANEL SUB-ASSY ,REAR DOOR ,LH Bent 1,294.90 FL 1 *LOCK ASSY ,REAR DOOR ,LH Repair 561.90 FL 1 *HING ASSY ,REAR DOOR ,UPPER LH Serviceable 98.90 FL 1 *HING ASSY ,REAR DOOR ,LOWER LH Serviceable 87.10 FL 1 *HING ASSY ,REAR DOOR ,LOWER LH Serviceable 183.80 FL 1 *MOULDING ASSY ,REAR DOOR BELT ,LH Serviceable 183.80 FL 1 *MOULDING ASSY ,REAR DOOR ,NO.3 LH Serviceable 113.50 FL 1 *TAPE ,BLACK OUT ,NO.1 REAR LH Necessary 21.90 FL 1 *TAPE ,BLACK OUT ,NO.2 REAR LH Necessary 15.40 FL 1 *TAPE ,BLACK OUT ,NO.3 REAR LH Necessary 15.40 FL 1 *TAPE ,BLACK OUT ,NO.3 REAR LH

Report was unsubmitted during this print-out.

Total Parts (S\$)

3,665.32

1,145.32

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
7	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
	Gross Labou	r Cost (S\$)	10,060.00	750.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >