

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20007379/KBA3Q2

**Date:** 18/08/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2018-00000503-01

**Claimant**  
**Vehicle No :** SGL5591G **Insured Vehicle No :** SCX9999Y

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: 1202000019141

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGL5591G</b>	Engine No:	R18A11039502
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16306S211935
Reg. Date:	21/09/2006 (Man. Year: 2006)	Odometer:	215914 km
Colour:	Metallic Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Grenlander 5 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 5 mm	Rear Right Side:	Grenlander 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,429.64	2,157.44	1,272.20	37.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,220.00	1,030.00	45.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,679.64</b>	<b>3,377.44</b>	<b>2,302.20</b>	<b>40.53</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>5,679.64</b>	<b>2,300.00</b>	<b>3,379.64</b>	<b>59.50</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (\$\$)</b>		360.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,667.45</b>		

### INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 16/07/2020 Inspected At:

Ngs Motorsport Pte Ltd - Ang Mo Kio (HQ)

Blk 10 Ang Mo Kio Ind Pk 2A, #02-01

AMK AutoPoint

Singapore 568047

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
<b>Parts:</b>	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGL5591G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	610.70 FL	*610.70 FL
2	1		*REAR BUMPER	Buckled	638.00 FL	*638.00 FL
3	2		*REAR BUMPER RETAINER LH/RH	Distorted	29.20 FL	*29.20 FL
4	1		*TAILLAMP RH/LH	N/S Serviceable / O/S Cut	617.40 FL	*308.70 FL
5	1		*BOOT LAMP RH/LH	N/S Cracked	604.40 FL	*302.20 FL
6	1		*END PANEL	Bent	300.50 FL	*300.50 FL
7	1		*REAR END GARNISH	Serviceable	65.10 FL	*- FL
8	1		*TRUNK RUBBER	Serviceable	199.50 FL	*- FL
9	1		*FENDER SHIELD	Serviceable	96.00 FL	*- FL
10	1		*REAR BOOT BADGE H	Necessary	25.70 FS	*25.70 FS
11	1		*REAR BOOT EMBLEM CIVIC	Necessary	43.90 FS	*43.90 FS
12	1		*REAR BOOT EMBLEM 1.8	Necessary	41.40 FS	*41.40 FS
13	1		*REAR BOOT I-VTEC	Necessary	50.00 FS	*50.00 FS
14	1		*REAR CAMERA	Serviceable	350.00 FS	*- FS
15	1		*REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
16	1		*REAR NO PLATE C/W CASING	Cracked	50.00 FS	*45.00 FS
17	15		*CLIPS FENDER SHIELD	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,061.80</b>	<b>2,595.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	632.16	437.86
<b>Total Parts (\$\$)</b>	<b>3,429.64</b>	<b>2,157.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT /ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,CUT & WELD PANEL ,REPAIR /RESHAPE DENTED BODY PANEL ,REPLACE DAMAGED PARTS ,REFIT INTO POSITION	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	CHECK WIRING /PROPER FUNCTION ON LIGHTS AND ETC	New	50.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,250.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >