

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20007380/KGA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00003279

Claimant
Vehicle No : SGU4942L **Insured Vehicle No :** FBL7406E

Date of Loss: 15/07/2020 Nature of Claim: TP Claim No: 1202000019175

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU4942L	Engine No:	1NZX543393
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305000977
Reg. Date:	16/05/2007 (Man. Year: 2007)	Odometer:	206276 km
Colour:	Black/White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,419.21	1,377.81	3,041.40	68.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	980.00	650.00	39.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,049.21	2,357.81	3,691.40	61.02
Approved Total (Overridden) (\$\$)		1,850.00		
Nett Amount (\$\$)	6,049.21	1,850.00	4,199.21	69.42
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		2,457.49		

INSPECTION

Date of Assignment: 16/07/2020

Date Inspected: 17/07/2020 Inspected At: Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU4942L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	447.25 FL	*447.25 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	65.40 FL	*65.40 FL
3	1		*RH HEADLAMP	Cut	383.50 FL	*383.50 FL
4	1		*FRONT RH FENDER	Repair	530.10 FL	*- FL
5	1		*FRONT RH FENDER UNDER SHIELD	Serviceable	158.40 FL	*- FL
6	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
7	1		*FRONT RH SHOCK ABSORBER	Serviceable	202.40 FL	*- FL
8	1		*FRONT RH LOWER ARM	Serviceable	256.30 FL	*- FL
9	1		*FRONT RH KNUCKLE ARM	Bent	421.60 FL	*421.60 FL
10	1		*FRONT RH WHEEL HUB & BEARING	Necessary	146.00 FL	*146.00 FL
11	1		*FRONT RH DRIVE SHAFT	Repair	958.00 FL	*- FL
12	1		*FRONT BUMPER LOWER SKIRTING	Serviceable	1,000.00 FS	*- FS
13	1		*FRONT RH TYRE	Serviceable	220.00 FS	*- FS
14	1		*FRONT RH SPORTS RIMS	Dented	500.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,318.95	1,743.75
- List Item Discount on L Items 25.00/25.00% (\$\$)	899.74	365.94
Total Parts (\$\$)	4,419.21	1,377.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	600.00	400.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	600.00	400.00
3	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE ,REFIT FRONT UNDER CARRIAGES	New	250.00	100.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
6	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,630.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >