

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 26L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL, SKIRT:R4, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	1,442.10	-
1	PANEL, SKIRT:R6, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	518.20	-
1	PANEL, SKIRT:R7, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	880.50	-
1	PANEL, SKIRT:R8, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	338.10	-
1	PANEL, SKIRT:R9, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	307.10	-
1	PANEL, SKIRT:R11, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	642.80	-
			4,128.80	-
	<u>SPECIAL NETT ITEMS</u>			
1	STICKER SG LOVE (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL, SKIRT:R4, FOR MB OC500 BUS, PANEL, SKIRT:R6, FOR MB OC500 BUS, PANEL, SKIRT:R7, FOR MB OC500 BUS, PANEL, SKIRT:R8, FOR MB OC500 BUS, PANEL, SKIRT:R9, FOR MB OC500 BUS AND PANEL, SKIRT:R11, FOR MB OC500 BUS.		1,325.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		942.00	772.00
			2,267.00	1,832.00
GRAND TOTAL			6,595.80	2,032.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,650.00

Report Ref No. NS/INC20007386/Qqf3e2


OI SUN PIN

Asst. Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.