

Your Ref: S9M0276C

Date: 04<sup>th</sup> Aug 2020

Our Ref: CS1/ASM20007392/Esf3e2

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Liu Yi Wen

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKJ 2933L  
INSURED VEHICLE: SJJ 3887S  
ACCIDENT DATE: 15/11/2019**

We thank you for your instruction on 16/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKJ 2933L from M/s Absolute Appraisal Services Pte Ltd.
- b) Survey report by LBS Automotive Appraisal Pte. Ltd. with colour photographs.
- c) Singapore Accident Statement of Vehicles SKJ 2933L, SKU 636A, SLC 8686K and SJJ 3887S
- d) Police Report of Vehicles SKJ 2933L and SLC 8686K.
- e) Final Repair Bill of SKJ 2933L from M/s MJE Motor.
- f) Colour damaged vehicle photographs of SKJ 2933L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKJ 2933L
Make & Model	: Mercedes Benz C 180 CGI
Chassis Number	: WDD2040492A405495
Year of Registration	: 2010
Engine Capacity	: 1796 cc

2. We recommend that the repairs of the entire damage require about 18 (Eighteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.