

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

Co. Reg. No. 201408536E

Block 8 Kensington Park Drive #01-07

Singapore 557323

Telephone: 62832866, 62816690 Facsimile: 62818748, 62832166

AUTOMOBILE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

OUR REFERENCE: LBS/AXA/TP/PRI/19/11/M146

REFERENCE : THIRD PARTY CLAIM- PRE-REPAIR INSPECTION

VEHICLE NUMBER : SKJ 2933L POLICY NUMBER : N.A.
ACCIDENT DATE : 15.11.2019 CLAIM NUMBER : S9M0276C - SKU 636A

PARTICULARS OF DAMAGED VEHICLE:

MAKE : MERCEDES BENZ C180 MODEL : 2010
COLOUR : BLUE MILEAGE KM : 217589
ENGINE CAPACITY : 1796CC V.I.N. : WDD2040492A405495

STATIC CHECKS: GENERAL CONDITION: GOOD

STEERING: SERVICEABLE

BRAKES: SERVICEABLE

TYRE CONDITIONS: SIZE: 225/45R17

FRONT O/S : 50% FRONT N/S : 50%
REAR O/S : 50% REAR N/S : 50%

Percentages denote the remaining estimated life of the tyre threads

ESTIMATED NORMAL PERIOD FOR REPAIR: 13 WORKING DAYS
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZED REPAIRS.

GENERAL DAMAGES

The impacts were confined to the front and rear portions of the vehicle

REMARKS

No estimate provided by workshop.

Economical Repair Value \$5,816.00 (Estimated Market Value \$29,000.00 less LTA rebate \$23,184.00)

Basing on visual inspection of the damage during the pre-repair survey, we opined the estimated repair cost to be in the region of \$8,000.00.

This pre-repair inspection was conducted on a "WITHOUT PREJUDICE" basis.

Vehicle inspected by : Mr Stan See Chew Seng
Date of Inspection : 26.11.2019
Surveyed at : MJE Motor
Date of Report : 16.12.2019

Damaged Automobile Appraisal
Traffic Accident Investigation and Reconstruction
A.D.R.: Mediation, Conciliation and Arbitration