

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16017693/ADA3Q2-1

Date: 25/08/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P0926241

Claimant

Vehicle No : SKN5670D

Insured Vehicle No :

PA7689Y

Date of Loss: 15/09/2016

Nature of Claim:

TP

Claim No: C0400141

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKN5670D

Make & Model:

AUDI A4, 1.8 TFSI MU (EU6) (A)

Engine No:

CJE078448

Reg. Date:

26/06/2014 (Man. Year: 2014)

Chassis No:

WAUZZZ8K8EA126886

Colour:

Bronze

Odometer:

45005 km

Engine Capacity:

1798 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/60 R16

Rear Tyre Size:

225/60 R16

Front Left Side:

Maxxis 6 mm

Rear Left Side:

Maxxis 6 mm

Front Right Side:

Maxxis 6 mm

Rear Right Side:

Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,447.00	2,840.40	3,606.60	55.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	1,380.00	3,450.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,277.00	4,220.40	7,056.60	62.58
+ GST 7.00/7.00% (S\$)	789.39	295.43	493.96	62.57
Nett Amount (S\$)	12,066.39	4,515.83	7,550.56	62.58
+ Car Rental (3.0 x S\$140.00/day + 7.00% GST) (S\$)		449.40		
(S\$)		4,965.23		
Liable Amount (50.00%) (S\$)		2,482.62		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,487.97		

INSPECTION

Date of Assignment: 19/09/2016

Date Inspected: 20/09/2016 Inspected At:

New Hock Teck Motor Workshop (HQ)
Blk 1, Kaki Bukit Avenue 6 #01-43,
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2017)
Parts:	143	AUDI A4 1.8 TFSI MU (EU6) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN5670D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Deformed	1,778.75 F	*1,778.75 FL
2	1		*REAR R/H BUMPER SIDE RETAINER (CONSISTENT)	Necessary	41.25 F	*41.25 FL
3	1		*REAR BUMPER REVERSE SENSOR (CONSISTENT) (2 PCS)	Damaged (1 PCS ONLY)	448.50 F	*224.25 FL
4	1		*REAR BUMPER LOWER (CONSISTENT)	Deformed	285.50 F	*285.50 FL
5	1		*REAR R/H TAIL LAMP (CONSISTENT)	Cut	826.25 F	*826.25 FL
6	1		*REAR R/H TAIL LAMP PANEL (CONSISTENT)	Not Necessary	293.00 F	*- FL
7	1		*REAR R/H BOOT LID SIDE REFLECTOR (CONSISTENT)	Not Necessary	688.75 F	*- FL
8	1		*REAR R/H FENDER (CONSISTENT)	Repair	1,551.25 F	*- FL
9	1		*REAR R/H FENDER GLASS (CONSISTENT)	Not Necessary	365.00 F	*- FL
10	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Not Necessary	168.75 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,447.00	3,156.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	315.60
Total Parts (S\$)	6,447.00	2,840.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	280.00	0.00
2	TO REMOVE & REFIT ROOF TOP CUSHION	New	380.00	0.00
3	TO REMOVE & REFIT PETROL TANK	New	280.00	0.00
4	TO REMOVE & REFIT FENDER GLASS	New	120.00	0.00
5	GUM	New	50.00	0.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
7	GUM	New	50.00	0.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
9	TUFF KOTE	New	150.00	0.00
10	TO CHECK WIRING	New	100.00	30.00
11	PANEL BEATING	New	1,600.00	600.00
12	SPRAY PAINTING	New	1,600.00	700.00
Gross Labour Cost (\$\$)			4,830.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >