



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007164
INV Date 21/10/2020
Reference CC4/FCI20002886/Kda3q2-
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMN 7758Z
Insured Veh. SHC 7547H
Claim No. D20001038MFSH
Policy No. D-20094921MFSH
Accident Date 15/02/2020
Inspection Date 26/02/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less: AC2004119 DD 26/05/2020	-306.00
Subtotal	44.00
GST (7%)	3.08
Grand Total	47.08

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20002886/Kda3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-05-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7547H	Veh. Inspected	SMN 7758Z	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20001038MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	18/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2040452A719080	Colour	METALLIC BLACK	
Odometer	125826	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/02/2020	Inspection Date	26/02/2020	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 7758Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N)	MTG CRACKED	1,704.00	1,460.00
1	REAR BUMPER CENTER CHROME (N)	NECESSARY	168.00	168.00
1	REAR BUMPER BEAM (N)	TO REPAIR SEE LABOUR	763.00	-
4	REAR BUMPER BEAM BRACKET @\$55.80 (N)	TO REPAIR SEE LABOUR	223.20	-
8	REAR BUMPER CLIP @\$8.00 (N)	NECESSARY	64.00	64.00
2	REAR BUMPER CHROME MOULDING SIDE @\$168.00 (N) (ADDITIONAL)	NECESSARY	336.00	280.00
1	TAIL LAMP LOWER BRACKET L/H (N) (ADDITIONAL)	CRACKED	95.00	95.00
1	REAR BUMPER SIDE RETAINER L/H (N) (ADDITIONAL)	DISTORTED	74.00	74.00
	LESS 5% DISCOUNT		-171.36	-
	LESS 10% DISCOUNT		-	-214.10
			3,255.84	1,926.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			280.00	-
<u>LABOUR</u>				
	SPRAY PAINT DAMAGED AREA AFFECTED .		980.00	280.00
	TO CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM AND REAR BUMPER BEAM BRACKET.		850.00	250.00
			1,830.00	530.00
GRAND TOTAL			5,365.84	2,456.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CC4/FCI20002886/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 7758Z

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 7758Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 7758Z

RE-INSPECTION

