

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20007397/ASF3E2

**Date:** 10/02/2021

### REFERENCE

Insured/Claimant:	ANNIE YEO WEI ZHEN	Policy No:	1900009384		
Date of Loss:	05/07/2020	Nature of Claim:	OD	Claim No:	3487966634SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW8805M		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC26014
Reg. Date:	24/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZ8V7K1013257
Colour:	Blue	Odometer:	34999 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,602.00	688.16	913.84	57.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,642.00	2,642.00	2,000.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,244.00</b>	<b>3,330.16</b>	<b>2,913.84</b>	<b>46.67</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	5,644.00	2,730.16	2,913.84	51.63
<b>+ GST 7.00/7.00% (S\$)</b>	395.08	191.11	203.97	51.63
<b>Nett Amount (S\$)</b>	<b>6,039.08</b>	<b>2,921.27</b>	<b>3,117.81</b>	<b>51.63</b>

### INSPECTION

Date of Assignment:	17/07/2020		
Date Inspected:	17/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	841.00 FS	*672.80 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - RH	Not Necessary	27.00 FS	*- FS
4	1		*FRONT FENDER BRACKET - RH	Not Necessary	38.00 FS	*- FS
5	1		*FRONT FENDER BRACE	Not Necessary	95.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	33.00 FS	*- FS
7	1		*WHEEL HOUSING LINER - RH	Not Necessary	167.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
9	1		*SUNDRIES	Necessary	200.00 FS	*15.36 FS
10	1		*FRONT FENDER INSULATION - RH	Not Necessary	42.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>1,602.00      688.16</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	350.00
2	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,642.00</b>	<b>2,642.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >